

TPMS SOFTWARE UPDATE



MaxiTPMS TS508, TS608, MS906TS, MS906Pro-TS

TS508 【Msts version: V6.45】 【Diag version: V1.96】
TS608 【Msts version: V6.36】 【Diag version: V1.92】
MS906TS 【Msts version: V6.34】 【Diag version: V1.89】
MS906Pro-TS 【Msts version: V1.17】 【Diag version: V1.13】

New:

1. Adds TPMS sensor coverage for 115 models in EU region including Mercedes CLE Class (2022/01-2023/12), Mercedes GLC Class (2022/06-2023/12), BMW 4 Series (2020/09-2023/12).
2. Adds TPMS sensor coverage for 150 models in US region including Cadillac Escalade DRW (2021/01-2023/12), Toyota Tacoma (2020/11-2023/06) and Chevrolet Tahoe DRW (2021/01-2023/12).
3. Adds TPMS sensor coverage for 74 models in KR region including Hyundai Ioniq 6 (2022/01-2023/12) and Hyundai Avante (2021/01-2023/12).
4. Adds TPMS sensor coverage for 58 models in JP region including Lexus LC Series (2021/11-2023/06) and Honda Odyssey (2017/01-2020/12).
5. Adds TPMS sensor coverage for 82 models in AU region including Mercedes CLS Class (2018/01-2023/12) and BMW 3 Series (2018/12-2023/12).
6. Adds diagnostic functions for Ford Transit (2021/01-2022/12), Qoros 5 (2020/09-2021/12), MG Mulan (2022/09-2023/06), DFM Forthing Yacht (2022/01-2023/12) and Forthing S60 EV (2022/01-2023/12).
7. Adds OBD Relearn function for Venucia D60 (up to 2022).

Optimization:

1. Optimizes OBD Relearn function for ChangAn, Hyundai & Kia Niro, Hongqi H7, DFM Forthing S50 EV and Ford Expedition.
2. Optimizes live data user interface for Toyota Sienna.
3. Fixes OBD Relearn failure for DFM Aeolus AX4, Renault Koleos, BYD (10 models including Song, Yuan and E6), Chery Tiggo 5, and Toyota Avalon.
4. Fixes system entry failure for DFM Fengguang E1 and Geely Binray.

