



MX-Sensor_V6.27 Function List For EU Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining(Red:New, Yellow: Modify)

Special Declaration:

1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.

2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| AIWAYS | U5 | 12/2019-04/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Dias | ● | ● |
| Abarth | 124 Spider | 10/2016-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Abarth | 124 Spider | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 4A Grande Punto | 01/2007-12/2010 | 433MHz | 199 | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| Abarth | 4B Punto EVO | 01/2010-12/2013 | 433MHz | 199 | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Abarth | 500 | 01/2008-12/2022 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Abarth | 500 | 01/2008-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 500C | 08/2011-11/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Abarth | 500C | 01/2010-06/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 595 | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 595 | 01/2014-12/2015 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Abarth | 595 C | 01/2015-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Abarth | 695 Biposto | 01/2015-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Abarth | 695 Biposto | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 81 Nuova Punto | 01/2012-12/2013 | 433MHz | 199 | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| Abarth | Punto Evo | 01/2013-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | Punto Evo | 01/2008-12/2013 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Acura | NSX | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Alfa Romeo | 159 | 07/2005-12/2016 | 433MHz | 939 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Alfa Romeo | 169 | 11/2015-12/2017 | 433MHz | N936 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Alfa Romeo | 4C | 01/2013-12/2021 | 433MHz | 960/961 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | 6C | 10/2016-06/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Alfa Romeo | 8C | 12/2006-12/2010 | 433MHz | 920 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Alfa Romeo | Brera | 01/2005-07/2012 | 433MHz | 939/946 | ● | ● | ○ | C | 433MHz | TRW | ● | ● |
| Alfa Romeo | Executive | 11/2018-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | GTA | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulia | 04/2014-12/2016 | 433MHz | UT | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulia | 01/2016-12/2021 | 50547691 433MHz | 952 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulia | 01/2020-12/2023 | 433MHz | 952 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulietta | 01/2010-12/2013 | 433MHz | | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| Alfa Romeo | Giulietta | 01/2010-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alfa Romeo | Giulietta | 01/2014-12/2022 | 433MHz | 940 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | Grand SUV | 11/2018-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Alfa Romeo | Kamal | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | MiTo | 08/2013-12/2020 | 433MHz | 955 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | MiTo | 01/2008-07/2013 | 433MHz | 955 | ● | ● | ○ | O | 433MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|--------------|-----------------|----------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Alfa Romeo | Quadrifoglio | 01/2018-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Quadrifoglio | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Spider | 06/2006-12/2017 | 433MHz | 946 | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| Alfa Romeo | Spider | 01/2015-06/2019 | 433MHz | J12A | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Alfa Romeo | Spider | 01/2006-12/2010 | 433MHz | 939 | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| Alfa Romeo | Stelvio | 01/2019-06/2024 | 433MHz | 949 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Stelvio | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Alpina | Alpina 10 | 01/1999-12/2004 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alpina | Alpina 12 | 01/1999-12/2001 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 3 | 10/2018-06/2021 | 433MHz | G20 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 3 | 05/1998-01/2008 | 433MHz | E46 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 3 | 01/1999-12/2002 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alpina | Alpina 3 | 06/2005-09/2009 | 433MHz | E90/E91/E92 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 3 | 09/2007-03/2014 | 433MHz | E90 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 3 | 01/2013-12/2019 | 433MHz | F30/F32 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | Alpina 4 | 09/2020-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 4 | 07/2013-08/2020 | 433MHz | F30/F32 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | Alpina 5 | 03/2014-01/2017 | 433MHz | F10 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 5 | 01/2017-12/2022 | 433MHz | G30 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | Alpina 5 | 01/2005-04/2010 | 433MHz | E60 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 5 | 01/2007-12/2010 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alpina | Alpina 5 | 01/2010-02/2014 | 433MHz | F10 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 6 | 03/2006-11/2010 | 433MHz | E63 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 6 | 12/2010-02/2014 | 433MHz | F12 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 6 | 03/2014-12/2019 | 433MHz | F12 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 7 | 01/2009-12/2015 | 433MHz | F01 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 7 | 01/2015-12/2022 | 433MHz | G11 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | Alpina 7 | 01/2001-12/2008 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina XB7 | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | B3 | 01/2005-09/2008 | 433MHz | E90/E91/E92 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 01/2004-12/2018 | 433MHz | F01 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Alpina | B8 | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | D3 | 01/2014-12/2022 | 433MHz | F30/F32 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | D3 | 01/2008-02/2014 | 433MHz | E90 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D4 | 07/2013-12/2021 | 433MHz | F30/F32 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | D5 | 04/2014-12/2021 | 433MHz | F10 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D5 | 02/2010-03/2014 | 433MHz | F10 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Roadster | 01/2003-12/2005 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alpina | XD3 | 09/2010-02/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XD3 | 09/2010-03/2014 | 433MHz | F25 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XD3 | 03/2014-06/2018 | 433MHz | F25 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XD3 | 01/2018-06/2022 | 433MHz | G01 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | XD4 | 09/2018-06/2022 | 433MHz | G02 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | Cygnat | 01/2011-06/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| Aston Martin | DB11 | 01/2016-12/2022 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|------------------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Aston Martin | DB9 | 01/2005-12/2011 | Smartire 433MHz | | ○ | ● | ○ | C | 433MHz | Smartire | ● | ● |
| Aston Martin | DB9 | 01/2009-12/2018 | 433MHz | AM803 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 09/2012-12/2015 | 433MHz | AM803 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 01/2018-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 01/2018-12/2022 | Schrader 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Aston Martin | DBS | 09/2007-12/2015 | 433MHz | V12 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS Superleggera | 01/2018-12/2022 | HY53SE360671 AA 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBS Superleggera | 01/2018-12/2022 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBX | 10/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBX | 04/2020-12/2022 | HUF 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBX | 10/2018-12/2021 | SCH 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | Lagonda | 01/2015-12/2019 | 433MHz | COMET | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | One-77 | 01/2011-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide | 03/2010-06/2021 | 433MHz | VH400 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide | 01/2010-12/2020 | 433MHz | F149 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide S | 01/2010-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vanquish | 10/2012-12/2020 | 433MHz | AM310 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 01/2019-12/2022 | 433MHz RDE036 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Aston Martin | Vantage | 07/2005-12/2021 | 433MHz | AM305 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 01/2005-12/2011 | Smartire 433MHz | | ○ | ● | ○ | C | 433MHz | Smartire | ● | ● |
| Aston Martin | Virage | 01/2010-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Zagato | 01/2011-08/2012 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Zagato | 09/2012-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A1 | 06/2010-06/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | A3 | 06/2012-12/2021 | 433MHz | 8L | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A3 | 01/2005-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A4 | 01/2012-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 | 08/2008-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A4 | 11/1996-12/2010 | 433MHz | B7 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 Allroad | 03/2009-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 Avant | 01/2001-12/2008 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 Avant | 01/2018-06/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A5 | 12/2006-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A5 | 09/2006-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 07/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 | 01/2011-12/2022 | 433MHz | 4G | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 06/2009-12/2011 | 433MHz | 4F | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 03/2014-12/2019 | 433MHz 7PP907275F | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2000-12/2005 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 05/2004-05/2011 | 433MHz 4F0907275D | 4B | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2009-12/2011 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | A6 Allroad | 01/2000-12/2007 | 433MHz | 4B | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 01/2004-10/2009 | 7P0907275F 433MHz | 4B | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 11/2009-12/2019 | 433MHz | 4G | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 01/2013-06/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 Allroad | 07/2017-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 Allroad | 10/2018-06/2022 | 433MHz 5Q0907275 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Avant | 07/2017-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Avant | 04/1997-02/2004 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Avant | 03/2004-06/2017 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Avant | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 Quattro | 01/2004-05/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Quattro | 06/2009-12/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Quattro | 01/2011-12/2015 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A7 | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A7 | 09/2010-12/2022 | 433MHz 5Q0907275 | 4G | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A7 | 01/2009-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2016-12/2022 | 433MHz 5Q0907275 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/1999-09/2002 | 433MHz | 4D | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2009-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A8 | 11/2009-10/2017 | 433MHz | 4H/4L | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 10/2002-12/2012 | 433MHz | 4E | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A9 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Allroad | 01/2000-12/2005 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | C-MPV | 03/2009-12/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q2 | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q2 | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q3 | 07/2011-12/2022 | 433MHz | 8U | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q3 | 06/2011-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q4 | 09/2019-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q5 | 01/2008-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q5 | 09/2008-06/2021 | 433MHz | 8R | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q7 | 01/2015-12/2021 | 433MHz | 4L/AU726 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 09/2005-12/2015 | 433MHz | 4L/AU716 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2016-12/2022 | MLB 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q8 | 01/2018-12/2022 | 433MHz | 4M | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2006-12/2022 | 433MHz 4F0907275D | AU714 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 06/2009-03/2015 | 433MHz 7PP907275F | AU714 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | R8 | 04/2015-06/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS Q3 | 01/2018-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 01/2013-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | RS3 | 07/2016-12/2022 | 433MHz | 8V | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 01/2008-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS4 | 04/2006-12/2018 | 433MHz | 8E/B7 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 01/2015-12/2022 | 5Q0907275 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2017-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS6 | 01/2019-12/2022 | 5Q0907275 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS6 | 01/2008-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2000-12/2007 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 04/2000-09/2005 | 433MHz | 4B | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 01/2008-12/2010 | 433MHz | C6 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 01/2020-03/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 01/2013-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2010-06/2021 | 433MHz 7PP907275F | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS7 | 03/2018-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RSQ8 | 12/2019-06/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | S1 | 01/2015-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S10 | 09/1999-10/2009 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | S3 | 01/2015-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S4 | 01/2003-12/2009 | 433MHz | B7 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 07/2009-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2000-12/2005 | 4D0907275 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2004-06/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 06/2018-12/2022 | 5Q0907275 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 11/2009-10/2017 | 433MHz | D4 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 10/2002-10/2009 | 433MHz | D3 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 09/1999-09/2002 | 433MHz | D2 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 10/2017-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S9 | 11/2009-10/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ2 | 01/2019-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ5 | 01/2014-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ5 | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ7 | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ7 | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ8 | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | TT | 03/2014-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TT | 04/2006-02/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TT | 02/2014-12/2022 | 433MHz | AU334 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | TT RS | 11/2016-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | TTS | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | TTS | 01/2012-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------|-----------------|--------------------------|---------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | e-tron | 01/2018-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BAIC | BJ40 | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | BJ40 PLUS | 01/2020-12/2021 | 433MHz B00019849 | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| BAIC | BJ40 PLUS | 01/2020-12/2021 | 433MHz B00011299 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BAIC | BJ40L | 06/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | BJ40L Golden | 06/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | BJ80 | 01/2016-06/2018 | 433MHz TP3040002 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | BJ80 | 01/2017-06/2019 | 433MHz 36380100B01000 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC | EC3 | 01/2019-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BAIC | EH Series | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | EU Series | 01/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | EU5 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | EV300 | 04/2018-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BAIC | ● | ● |
| BAIC | EX3 | 06/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | EX5 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | S3L | 01/2016-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC | S5 | 01/2017-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC | S6 | 11/2015-06/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | BAIC | ● | ● |
| BAIC | S7 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC | Senova CC | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | Senova D20 | 01/2019-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BAIC | Senova D50 | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | Senova D50 | 07/2019-12/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BAIC | Senova D70 | 01/2013-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | Senova X35 | 01/2016-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | Senova X55 | 01/2016-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | Senova X55 | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | Senova X65 | 01/2015-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | WeiWang S50 | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC | Zhida | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | 1 Series | 07/2019-12/2022 | 433MHz | F40 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 07/2010-07/2019 | 433MHz | F20/F21 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 1 Series | 01/2007-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 1 Series | 12/2006-08/2010 | 433MHz | E88/E82 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 06/2004-02/2014 | OYGTSSRE4D 433MHz | E88/E82 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 03/2014-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 2 Gran Coupe | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 11/2019-12/2022 | 433MHz | F44 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 01/2014-12/2022 | 433MHz | F22/F23/F45 /F46 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series | 03/2019-12/2022 | 433MHz | G21/G28 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 10/2017-12/2022 | 433MHz | G20 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------|-----------------|-----------------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | 3 Series | 01/2014-12/2019 | 433MHz | F30/F31/F35 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series | 10/2010-03/2014 | 433MHz | F30 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 09/2009-02/2014 | 433MHz | E9x | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 01/2005-08/2009 | 433MHz | E9x | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 03/1999-12/2011 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 3 Series | 01/1999-12/2004 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 01/1998-06/2008 | 433MHz | E46 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series GT | 03/2014-06/2021 | 433MHz | F34 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series GT | 01/2013-02/2014 | 433MHz | F34 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 01/2013-12/2020 | OYGTSSRE4DB 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 09/2020-12/2022 | 433MHz | G22 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 07/2013-12/2020 | 433MHz | F32/F33/F36 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 5 Series | 09/1998-05/2004 | 433MHz | E39 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 01/2017-12/2022 | 433MHz | G30/G31/G38 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 5 Series | 03/2014-12/2017 | 433MHz | F07/F10/F11 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 09/2010-02/2014 | 433MHz | F10/F11/F07/F18 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 05/2003-11/2010 | 433MHz | E60/E61/F07 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 01/2001-12/2009 | 433MHz | E65 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 01/2009-12/2017 | 433MHz | F10/F07 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 04/2014-12/2018 | 433MHz | F07 LCI | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 01/2017-12/2019 | 433MHz | G32 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 6 Series | 01/2004-12/2007 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 6 Series | 01/2010-02/2014 | 433MHz | F12/F13/F06 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 03/2014-12/2022 | 433MHz | F12/F13/F06 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 08/2003-10/2011 | 433MHz | E63/E64 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series GT | 09/2016-12/2022 | 433MHz | G14/G32 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 03/2014-05/2015 | 433MHz | F01/F02/F03/F04 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 10/2014-12/2022 | 433MHz | G11/G12 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 01/2008-02/2014 | 433MHz | F01/F02/F03/F04 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 01/2001-09/2010 | 433MHz | E65/E66 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 01/2001-12/2008 | 433MHz | E66 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 09/1998-12/2005 | 433MHz | E38 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 8 Series | 07/2018-12/2022 | 433MHz | G15 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | Coupe | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M2 | 11/2014-12/2021 | 433MHz | F87 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M3 | 01/1999-12/2006 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M3 | 01/2007-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M3 | 01/2010-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M3 | 01/2014-12/2019 | 433MHz | F80 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M3 | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M4 | 04/2014-12/2021 | 433MHz | F82/F83 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M4 | 10/2014-12/2020 | HUF 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 03/2014-12/2017 | 433MHz | F10 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | M5 | 01/2003-12/2009 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 01/1999-12/2003 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M5 | 01/2005-12/2010 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M5 | 09/2010-03/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 01/2016-12/2022 | 36106872774 433MHz | F90 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M5 | 01/2018-12/2021 | 433MHz | F90 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M6 | 06/2011-12/2015 | 36106856227 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 03/2014-12/2018 | 433MHz | F12 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 01/2005-12/2011 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M7 | 03/2014-12/2017 | 433MHz | F01 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M8 | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | Motorcycle | 01/2010-12/2019 | 433MHz | | ○ | ○ | ○ | | 433MHz | Schrader | Activate Only | ● |
| BMW | Ms Competition | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| BMW | X1 | 03/2014-06/2016 | 433MHz | E84 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 09/2008-02/2014 | 433MHz | E84 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 08/2015-12/2022 | 433MHz | F48 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X2 | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X3 | 01/2003-12/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X3 | 03/2003-07/2011 | 433MHz | E83 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 01/2017-12/2022 | 433MHz | G01/G08 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X3 | 04/2014-12/2017 | 433MHz | F25 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 11/2010-03/2014 | 433MHz | F25 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 05/2013-12/2019 | 433MHz | F26 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 03/2017-12/2022 | 433MHz | G02 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X5 | 11/2006-09/2010 | 433MHz | E70 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 01/2007-12/2010 | Indirect | E70 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X5 | 10/2010-06/2013 | 433MHz | E70 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 05/2013-12/2019 | 433MHz | F15/F85 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X5 | 09/2017-12/2022 | 433MHz | G05 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X5 | 10/1999-09/2007 | 433MHz | E53 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 01/2005-12/2006 | Indirect | E53 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X6 | 09/2019-12/2022 | 433MHz | G06 | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | X6 | 12/2011-07/2014 | 433MHz | E71 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 12/2007-11/2011 | 433MHz | E71 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 08/2014-12/2019 | 433MHz | F16/F86 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X6 HYBRID | 07/2012-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 HYBRID | 10/2008-10/2011 | 433MHz | E72 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X7 | 01/2018-12/2022 | 433MHz | G07 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | Z4 | 03/2014-02/2019 | 433MHz | E89 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 11/2018-12/2022 | 433MHz | G29 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 10/2002-12/2011 | 433MHz | E86/E89 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 01/2006-02/2014 | 433MHz | E89/E71 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 01/2003-12/2008 | Indirect | E85/E86 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | Z4 | 03/2019-06/2020 | 433MHz | G02 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | i3 | 01/2013-06/2022 | 433MHz | I01/I12 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | i4 | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i8 | 01/2013-12/2019 | 433MHz | I01/I12 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | ix | 01/2021-12/2022 | Huf 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | ix | 11/2020-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | ix3 | 11/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BORGWARD | BX5 | 01/2016-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| BORGWARD | BX7 | 01/2016-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| BYD | E2 | 09/2019-06/2021 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | E3 | 08/2020-06/2021 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | E5 | 01/2016-03/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | E5 | 04/2018-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | E6 | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | F3 | 09/2019-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | F3 | 09/2019-06/2021 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | G5 | 01/2014-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | G6 | 01/2011-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Han | 01/2020-06/2021 | SCH 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BYD | Qin | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Qin | 11/2019-12/2020 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin EV | 11/2019-12/2020 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin NEW | 11/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Qin NEW | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin Pro | 01/2018-12/2020 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | S2 | 06/2019-12/2020 | Baolong 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| BYD | S7 | 01/2015-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Sirui | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Song | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Song | 03/2020-12/2020 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BYD | Song | 01/2018-06/2019 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Song | 04/2017-12/2018 | S6DM3609200 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song MAX | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song Max | 03/2019-12/2020 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song Pro | 07/2019-12/2020 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song Pro New | 07/2019-12/2020 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Surui | 01/2015-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Surui | 01/2015-12/2016 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Tang | 01/2018-06/2021 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Tang | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BYD | Tang | 01/2015-12/2017 | 433MHz 6B3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Tang DM | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Tang EV | 01/2018-12/2020 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Tang EV | 01/2021-12/2021 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Tang EV | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Yuan | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Yuan | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Yuan EV | 09/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Yuan EV | 01/2018-08/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Yuan EV | 01/2019-12/2020 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Bentley | Arnage | 01/2008-09/2011 | 7PP907275F 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Azure | 01/2006-12/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Bentayga | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Brooklands | 01/2008-12/2011 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Bentley | Brooklands Coupe | 01/2008-06/2016 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 03/2014-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2003-12/2004 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2005-03/2013 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental Flying Spur | 03/2005-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 09/2003-05/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 06/2005-12/2021 | 433MHz BY634 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 04/2018-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GTC | 01/2018-12/2021 | 5Q0907275 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GTC | 01/2006-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Bentley | E-CUV | 11/2014-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2011-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2019-12/2022 | 5Q0907275 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Bentley | GTC | 07/2006-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulliner | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2001-12/2020 | 7PP907275F 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BlueSG | Car Share | 01/2011-12/2011 | 433MHz | | ○ | ● | ○ | C | 433MHz | LDL Technology | ● | ● |
| Bugatti | Chiron | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bugatti | Royale | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bugatti | Veyron | 01/2005-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bugatti | Vitesse | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Buick | Park Avenue | 01/1997-12/2005 | 433MHz | G-CAR | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| CMC | A180 | 07/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------|-----------------|--------------------|-----------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| CMC | A190 | 07/2016-12/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| CMC | VERYCA | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| CMC | ZINGER | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2012-12/2012 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2014-12/2014 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2015-12/2015 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2016-12/2020 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2020-12/2020 | 433MHz 13529770 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2013-12/2013 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2015-12/2015 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | BLS | 01/2006-12/2011 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2020-12/2022 | 433MHz 13530661 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2019-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2016-12/2021 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2019-12/2022 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2014 | 433MHz | GMX206/ GMX226 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 06/2013-12/2013 | 433MHz | A1LL | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 06/2013-12/2013 | 433MHz | GMX322 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2010-12/2013 | 433MHz | GMX206/ GMX226 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2009-12/2009 | 433MHz | GMX206/ GMX226 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2016 | 433MHz | GMX322 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2015-12/2015 | 433MHz | GMX206/ GMX226 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2016-06/2021 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2017-12/2019 | 433MHz | GMX322 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2008-12/2008 | 433MHz | GMX206/ GMX226 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2006-12/2007 | 433MHz | GMX322 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2016-12/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ELR | 01/2016-06/2018 | 433MHz | D1BLI | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2013-12/2013 | 433MHz | GMT900/ GMTK2XL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2015-12/2020 | 433MHz | GMT900/ GMTK2XL/ K2UL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2014-12/2014 | 433MHz | GMT900/ GMTK2XL/ K2UL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 12/2005-12/2006 | 433MHz | GMT926 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2021-12/2022 | 433MHz 13533166 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|------------|-----------------|----------------------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Cadillac | Escalade | 01/2012-12/2012 | 433MHz | GMT900/GMTK2XL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2009-12/2011 | 433MHz | GMT926 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2007-12/2008 | 433MHz | GMT926 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2005-12/2006 | 433MHz | GMT265 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2016-12/2016 | 433MHz | C1UL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2014-12/2016 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2013-12/2013 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2010-12/2012 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2009-12/2009 | 433MHz | GMT265 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 06/2008-12/2009 | 433MHz 25789964 | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2007-12/2008 | 433MHz | GMT265 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2008-09/2012 | 433MHz | GMX295 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2005-12/2007 | 433MHz | GMX295 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XLR | 08/2003-02/2011 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT4 | 11/2018-12/2022 | 433MHz | E2UL | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2016-06/2021 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2018-12/2022 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT6 | 01/2019-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2015-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2013-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2012-12/2012 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| ChangAn | CS15 | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS35 | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS35 | 01/2015-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS35 PLUS | 01/2018-05/2019 | Hi Confi 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS55 | 01/2017-06/2020 | Hi Confi 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS55 | 01/2017-06/2020 | Lo Confi 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 | 01/2014-12/2016 | 4WD 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 | 01/2014-12/2016 | 2WD 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 | 01/2017-12/2019 | 2WD 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS85 | 03/2019-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS85 COUPE | 03/2019-12/2020 | 433MHz 3601010W10 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS95 | 01/2019-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS95 | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CX70 | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | EADO | 03/2020-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | EADO | 05/2019-12/2020 | Hi Confi 433MHz 3601010W10 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | EADO | 01/2018-02/2020 | Hi Confi 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------------|-----------------|----------------------|-------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| ChangAn | EADO EV460 | 03/2020-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | LINMAX | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | OuShang | 01/2017-12/2020 | 3B 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | OuShang | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | OuShang X70A | 03/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | Raeton | 01/2013-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | Raeton | 01/2017-12/2018 | 433MHz 3601010W10 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | Raeton CC | 01/2017-12/2020 | Hi Confi 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | Raeton CC | 01/2017-12/2020 | Lo Confi 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | ARRIZO 5 | 07/2018-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | ARRIZO 5 | 01/2016-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | ARRIZO 5e | 04/2019-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | ARRIZO GX | 01/2019-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Arrizo | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chery | E3 | 01/2013-12/2015 | 433MHz (Baolong) | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | E3 | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Chery | ● | ● |
| Chery | EQ1 | 01/2018-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Fulwin | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chery | QQ | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chery | Tiggo | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chery | Tiggo 3 | 07/2018-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 3 | 01/2016-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 3xe | 01/2018-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 3xe | 07/2018-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 5 | 01/2013-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 5e | 01/2017-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 5e | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 7 | 01/2018-06/2020 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 7 | 06/2016-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 7 | 07/2018-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 8 | 01/2018-06/2018 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 8 | 01/2018-04/2020 | VDO 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 8 PLUS | 10/2020-10/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Chery | Tiggo e | 04/2020-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chevrolet | Aveo | 01/2006-12/2010 | 433MHz | G1SC/ G1JC/ T300 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2015-06/2020 | 433MHz | G1SC/G1JC/T 250/T300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2013-12/2014 | 433MHz | G1SC/G1JC/T 250/T300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 06/2012-12/2012 | 433MHz | G1SC/ G1JC/ T300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------------|-----------------|--------------------|---------------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Aveo | 01/2011-05/2012 | 433MHz | GISC/ G1JC/ T300 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Bolt EV | 01/2017-12/2020 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2014-12/2015 | 433MHz | GMX521 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2017-06/2022 | 433MHz | 1AG37/ A1BC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2013-12/2013 | 433MHz | GMX521 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2012-12/2012 | 433MHz | GMX521 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2016 | 433MHz | 1AG37/ A1BC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2010-12/2011 | 433MHz | GMX521 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 01/2009-12/2011 | 433MHz | C100 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 06/2006-12/2008 | 433MHz | C100 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 01/2012-12/2019 | 433MHz 25789964 | C100 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 01/2021-12/2021 | 433MHz | | ● | ● | ● | O | 433MHz | Baolong | ● | ● |
| Chevrolet | Cobalt | 01/2012-12/2014 | 433MHz | G1LC | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2015-12/2019 | 433MHz | G1LC | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2013-12/2017 | 433MHz | GMI700 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 07/2011-12/2012 | 433MHz | GMI700 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado (LCV) | 01/2003-06/2006 | 433MHz | GMT355 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado (LCV) | 07/2006-12/2012 | 433MHz | GMT355 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2014-12/2019 | C7 433MHz | Y1BC | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2015-12/2019 | C7 433MHz | GMX245 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 06/2004-12/2009 | C6 433MHz | GMX245 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2010-12/2013 | C6 433MHz | GMX245 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 02/2020-12/2022 | 433MHz | Y2XC | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2019-06/2021 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2016-12/2018 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2013-12/2015 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2012-12/2012 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2011-12/2011 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 10/2008-12/2010 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Epica | 01/2006-12/2011 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------------|-----------------|--------------------|----------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Equinox | 01/2018-12/2020 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2014-12/2022 | 433MHz | GMT610 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2009-12/2013 | 433MHz | GMT610 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 07/2007-12/2008 | 433MHz | GMT610 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 07/2002-06/2007 | 433MHz | GMT610 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Lacetti | 06/2003-12/2014 | Clamp in 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Lacetti | 06/2003-12/2014 | Snap in 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2017-12/2022 | 433MHz | V300 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2016-12/2016 | 433MHz | V300/ GMX351/ GMX386 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2014-12/2015 | 433MHz | V300/ GMX351/ GMX386 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2013-06/2014 | 433MHz | V300 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2012-12/2012 | 433MHz | V300 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2011-06/2012 | 433MHz | V300 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 06/2010-06/2011 | 433MHz | V300 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Matiz | 06/2014-06/2021 | 433MHz | M100 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Matiz | 04/2005-06/2014 | 433MHz | M200 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Matiz | 01/1998-03/2005 | 433MHz | M100 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Niva | 01/2014-12/2022 | 433MHz | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2017-06/2021 | 433MHz | J309 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2015-12/2016 | 433MHz | J309/D1NC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2013-12/2014 | 433MHz | J309 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2012-12/2012 | 433MHz | J309 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 09/2010-12/2011 | 433MHz | J309 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2015-12/2020 | 433MHz | K2XC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 07/2013-12/2014 | 433MHz | K2XC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2016-12/2022 | 433MHz | M1JC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2015-12/2015 | 433MHz | M1JC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2013-12/2014 | 433MHz | M1JC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 07/2009-12/2012 | 433MHz | M1JC | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2005-06/2009 | 433MHz | M200 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2021-12/2022 | 433MHz 13533166 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2016-12/2018 | 433MHz | GMT931 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2015-12/2015 | 433MHz | GMT931 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2014-12/2014 | 433MHz | GMT931 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2009-12/2013 | 433MHz | GMT931 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2007-12/2008 | 433MHz | GMT931 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2006-12/2006 | 433MHz | GMT931 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2022 | 433MHz 13533166 | | ○ | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 07/2020-12/2021 | 433MHz | T1UC | ● | ● | ● | O | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Tahoe | 01/2016-06/2020 | 433MHz | GMT921 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2015-12/2015 | 433MHz | GMT921 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2014-12/2014 | 433MHz | GMT921 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2015-12/2022 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2013-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2013-12/2014 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2009-12/2012 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2006-12/2008 | 433MHz | GMT360 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2001-12/2005 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2018-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2010-12/2012 | 433MHz | C105 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2013-12/2014 | 433MHz | G1UC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2012-12/2012 | 433MHz | G1UC | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2015-12/2022 | 433MHz | G1UC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 06/2015-08/2019 | 433MHz | D2JCI | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2015-12/2015 | 433MHz | D1JCI | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2013-12/2014 | 433MHz | D1JCI | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 06/2010-12/2012 | 433MHz | D1JCI | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2016-12/2018 | 433MHz | D1JCI | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chrysler | 200 | 01/2015-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Chrysler | 300 | 01/2018-12/2021 | 433MHz | LE48 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2014-12/2017 | 433MHz | LE48 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2014-12/2017 | 433MHz | LX | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2011-12/2013 | 433MHz | LX | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2009-12/2010 | 433MHz | LX | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 06/2004-06/2011 | 433MHz | LE48 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 01/2018-06/2021 | 18 inch 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 01/2018-06/2021 | 20 inch 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 06/2009-12/2017 | 20 inch 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 06/2009-12/2017 | 18 inch 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 06/2005-05/2009 | 433MHz | LE48 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Chrysler | Crossfire | 10/2003-01/2009 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chrysler | Delta | 01/2013-12/2017 | 433MHz | 844 | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Chrysler | Delta | 01/2008-12/2012 | 433MHz | | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| Chrysler | Grand Voyager | 01/2016-12/2017 | 433MHz | RU | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Chrysler | Grand Voyager | 01/2011-12/2017 | 433MHz | RT | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chrysler | Grand Voyager | 01/2018-03/2020 | 433MHz | RT | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chrysler | Grand Voyager | 01/2018-12/2019 | 433MHz | RU | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Chrysler | Grand Voyager | 01/2007-12/2010 | 433MHz | RT | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Pacifica | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Chrysler | Pacifica | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Chrysler | Pacifica | 01/2004-12/2005 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chrysler | Sebring | 06/2006-12/2015 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2014-12/2016 | 433MHz | RT | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2011-12/2013 | 433MHz | RT | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2007-12/2010 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Viper | 09/2012-12/2017 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Voyager | 01/2018-12/2019 | 433MHz | RT | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Voyager | 01/2011-12/2017 | 433MHz | RT | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Voyager | 01/2007-12/2010 | 433MHz | RT | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Chrysler | Ypsilon | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Ypsilon | 01/2018-06/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Chrysler | Ypsilon | 04/2011-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Ypsilon | 01/2011-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Chrysler | Ypsilon | 01/2008-03/2011 | 433MHz | | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| Citroen | Berlingo | 03/2016-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | Berlingo | 01/2008-09/2013 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Berlingo | 10/2013-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C-Cactus | 07/2014-12/2016 | 433MHz | B71 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Citroen | C-Elysee | 09/2012-12/2021 | 433MHz | M3/M4 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Citroen | C-ZERO | 01/2011-06/2021 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Continental | ● | ● |
| Citroen | C1 | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C3 | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Citroen | C3 | 01/2010-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | C3 | 01/2009-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C4 | 01/2013-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | C4 | 09/2004-07/2010 | 433MHz | B5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C4 | 01/2004-09/2014 | 433MHz | B53/B7 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C4 | 10/2013-12/2019 | 433MHz | B58 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | C4 Aircross | 04/2012-12/2021 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Continental | ● | ● |
| Citroen | C4 Cactus | 01/2014-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | C5 | 08/2004-08/2013 | 433MHz | X3/X40 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C5 | 12/2000-07/2004 | 433MHz | X40 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C5 | 09/2013-12/2020 | 433MHz | X7 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | C5 Aircross | 01/2018-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C5 II(RC_) | 06/2004-12/2013 | 433MHz | X3/X40 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C5(LCV) | 10/2007-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C6 | 01/2005-12/2013 | 433MHz | X6 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C8 | 10/2005-12/2015 | 433MHz | V3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C8 | 01/2002-09/2005 | 433MHz | V3 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C8 | 07/2014-06/2018 | 433MHz | A55 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | DS3 | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | DS3 | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS3 | 12/2009-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS4 | 02/2014-12/2020 | 433MHz | B81 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | DS4 | 01/2010-01/2014 | 433MHz | B75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS4 Crossback | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS4(LCV) | 12/2010-01/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Citroen | DS5 | 02/2014-12/2019 | 433MHz | X2/50 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS5 | 01/2011-01/2014 | 433MHz | B81 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS5 (LCV) | 06/2011-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS6 | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS7 | 03/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS7 | 01/2018-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | DS9 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | E-Mehari | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | Jumper | 05/2006-04/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Jumper | 01/2006-05/2014 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumper Combi | 01/2014-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | Jumper Combi 2 | 07/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumper Combi 2 | 01/2006-06/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumper/Relay | 05/2014-06/2021 | VAN 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | Jumper/Relay | 05/2014-12/2019 | BUS 433MHz | B58 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumpy Combi 3 | 01/2017-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Jumpy/Dispatch | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Jumpy/Dispatch | 11/2013-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumpy/Dispatch | 01/2007-06/2014 | 433MHz 9677130580 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Landtrek | 01/2019-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Citroen | Nemo | 01/2008-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Nemo | 10/2007-09/2014 | 433MHz | B53/B7 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | Nemo | 10/2014-12/2019 | 433MHz | B53/B7 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Citroen | Relay | 05/2006-05/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Relay | 01/2013-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | Space Tourer | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| DFM | 560 | 06/2019-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFM | 580 | 01/2017-12/2021 | SA02/SA03 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | 580 | 01/2017-12/2019 | SA04 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFM | 580 | 01/2016-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFM | C32/C35 | 01/2018-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| DFM | CM7 | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | CM7 | 01/2014-12/2016 | Snap in 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| DFM | DFPV A30 | 01/2017-12/2017 | 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| DFM | DFPV A9 | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| DFM | DFPV AX3 | 11/2018-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| DFM | DFPV AX4 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | DFPV AX5 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | DFPV AX7 | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| DFM | DFPV AX7 | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | DFPV E70 | 09/2019-12/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| DFM | EC31 | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| DFM | EC35 | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| DFM | F5 | 01/2018-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| DFM | F600 | 01/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | Jingyi S50 | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | Jingyi S50 EV | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| DFM | Jingyi S50 EV | 01/2018-06/2019 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | Jingyi X5 | 06/2017-12/2019 | Continental 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| DFM | Jingyi X5 | 01/2014-06/2019 | Snap in 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| DFM | Jingyi X5 | 01/2014-06/2019 | Clamp in 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | Ling zhi | 04/2020-06/2021 | BaoLong 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| DFM | M6 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| DFM | M6 | 01/2018-12/2019 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | M7 | 01/2018-12/2019 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | M7 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| DFM | MX5 | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | MX6 | 07/2015-12/2016 | 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| DFM | MX6 | 01/2015-12/2016 | QY1036 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| DFM | S330 | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| DFM | S370 | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| DFM | S500 | 11/2015-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | S560 | 01/2018-06/2021 | SA04 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFM | S560 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFM | S560 | 01/2018-06/2019 | SA02/SA03 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | SX6 | 01/2018-12/2019 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | SX6 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | Seres 3 | 01/2020-12/2021 | SA02/SA03 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| DFM | Seres 5 | 01/2020-12/2021 | SA02/SA03 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| DFM | T5 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| DFM | T5 | 01/2018-12/2019 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | X6 | 01/2017-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | ix5 | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFM | ix7 | 11/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DR Auto | DR 4 | 01/2017-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| DR Auto | DR 5 | 01/2018-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| DR Auto | DR 6 | 01/2017-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| DR Auto | DR EVO | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| DR Auto | DR F35 | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Dacia | Dokker | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Dokker | 01/2012-12/2021 | SD 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|----------------|-----------------|-----------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Dacia | Duster | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Duster | 02/2010-06/2021 | SD 433MHz | H79 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dacia | Duster | 01/2018-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Dacia | Kwid | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Dacia | Lodgy | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Lodgy | 01/2012-12/2021 | SD 433MHz | J92 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dacia | Logan | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Logan | 02/2010-12/2021 | SD 433MHz | L52/K52 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dacia | Oroch Pickup | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Oroch Pickup | 01/2016-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Dacia | Sandero | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Sandero | 10/2012-12/2021 | SD 433MHz | B52 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dacia | Spring | 01/2021-12/2022 | 433Mhz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Dacia | Stepway II | 01/2013-12/2018 | SD 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Daewoo | Genra | 04/2004-12/2020 | 433MHz | J200 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Daewoo | Matiz Kasten | 09/1998-06/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Daewoo | Nexia | 11/1995-12/2016 | 433MHz | T-CAR | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Dodge | Avenger | 01/2014-12/2014 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Avenger | 01/2006-12/2013 | 433MHz | JS41D | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Caliber | 01/2006-12/2012 | 433MHz | PM49 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Caravan | 06/2011-12/2017 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2018-12/2018 | 433MHz | LC22 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2014-12/2017 | 433MHz | LC22 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2011-12/2013 | 433MHz | LC22 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2008-12/2010 | 433MHz | LC22 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2019-06/2021 | 433MHz | LC22 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Challenger SRT | 01/2018-12/2021 | 433MHz | LD | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger SRT | 01/2015-12/2017 | 433MHz | LD | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2018-12/2021 | 433MHz | LX48D/LD | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 10/2014-07/2017 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2014-09/2014 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2011-12/2013 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2010-12/2010 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2009-12/2009 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 08/2017-12/2017 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2015-12/2015 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2018-06/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Dakota | 01/2014-12/2015 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Dakota | 01/2012-12/2013 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Dakota | 01/2009-12/2011 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Durango | 01/2018-12/2021 | 433MHz | WD75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Durango | 01/2014-12/2017 | 433MHz | WD75 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Durango | 01/2011-12/2013 | 433MHz | WD75 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Durango SRT | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Dodge | Grand Caravan | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|---------------|-----------------|----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Dodge | Grand Caravan | 01/2014-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2011-12/2013 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2008-12/2010 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Dodge | Journey | 01/2018-12/2021 | 433MHz | JC49 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2011-12/2017 | 433MHz | JC49 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2008-12/2010 | 433MHz | JC49 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Dodge | Nitro | 06/2006-12/2012 | 433MHz | KA | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 1500 | 01/2019-12/2022 | DT 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram Series | 01/2006-12/2009 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Dodge | Ram Series | 01/2010-12/2013 | 433MHz | DS/DJ | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Ram Series | 01/2014-12/2017 | 433MHz | DS/DJ | ● | ● | ● | 0 | 433MHz | TRW | ● | ● |
| Dodge | Ram Series | 01/2018-12/2021 | 433MHz | DS/DJ | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Dodge | SRT Viper | 01/2010-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Viper | 01/2013-12/2016 | 433MHz | ZD | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| EXEED | TXL | 07/2020-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAW | BESTURN B30 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | BESTURN B50 | 01/2011-12/2016 | Lear 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| FAW | BESTURN B50 | 01/2012-12/2016 | TRW 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| FAW | BESTURN B50F | 01/2015-06/2018 | Baolong 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAW | BESTURN B50F | 01/2015-06/2018 | 433MHz | | ○ | ● | ○ | C | 433MHz | FAW | ● | ● |
| FAW | BESTURN B70 | 10/2017-06/2019 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | BESTURN B70 | 01/2012-12/2016 | Lear 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| FAW | BESTURN B70 | 01/2012-06/2019 | TRW 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| FAW | BESTURN B90 | 01/2012-12/2016 | TRW 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| FAW | BESTURN B90 | 01/2012-12/2016 | Lear 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| FAW | BESTURN T77 | 01/2019-12/2019 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | BESTURN T77 | 01/2017-12/2017 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | BESTURN X40 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| FAW | BESTURN X80 | 07/2016-06/2019 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | BESTURN X80 | 01/2013-06/2016 | Lear 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| FAW | BESTURN X80 | 01/2013-06/2016 | TRW 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| FAW | BESTURN X80F | 09/2016-06/2019 | Baolong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | HongQi H5 | 01/2017-12/2018 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | HongQi H7 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| FAW | HongQi H7 | 01/2016-12/2016 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | HongQi H7 | 01/2014-12/2017 | 433MHz | | ○ | ● | ○ | C | 433MHz | Lear | ● | ● |
| FAW | HongQi HS5 | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAW | Junpai A70 | 01/2016-12/2016 | 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAW | Junpai A70E | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAW | Junpai D60 | 07/2016-12/2017 | New 433MHz | | ● | ● | ○ | S | 433MHz | Xiali | ● | ● |
| FAW | Junpai D60 | 10/2014-06/2016 | 433MHz | | ● | ● | ○ | S | 433MHz | Xiali | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|------------------|-----------------|---------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| FAW | SENIA R7 | 01/2016-06/2019 | Lo Confi 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | SENIA R7 | 01/2016-06/2019 | Hi Confi 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAW | SENIA R9 | 01/2018-12/2019 | Lo Confi 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | SENIA R9 | 01/2016-06/2019 | Hi Confi 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Ferrari | 360 Spider | 07/2007-07/2009 | 433MHz | F131 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Italia | 09/2007-12/2013 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Italia | 01/2014-12/2015 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Speciale | 01/2013-12/2016 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Spider | 01/2009-12/2020 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 488 | 01/2015-12/2021 | 433MHz | F142 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 550 Maranello | 01/2002-12/2006 | 433MHz | F133e | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 550 Maranello | 01/1997-12/2001 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 575M Maranello | 01/2002-12/2006 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 599 GTB | 01/2004-12/2014 | 433MHz | F141 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 599 GTO | 01/2004-12/2012 | 433MHz | F141 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 612 Scaglietti | 01/2004-12/2011 | 433MHz | F137 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 812 Superfast | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | CTC4 Lusso T | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | California | 10/2008-12/2017 | 433MHz | F149 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Enzo | 01/2002-12/2006 | 433MHz | F140 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 01/2012-12/2022 | 433MHz | F151/ F152 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 01/2016-12/2020 | 433MHz | F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 tdf | 01/2015-12/2021 | 433MHz | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 09/2004-06/2007 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 01/2007-12/2009 | 433MHz | F131EVO | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 07/2007-10/2009 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 Scuderia | 07/2007-04/2013 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 Spider | 01/2014-12/2018 | 433MHz | F149 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F550/575 | 01/1996-11/2009 | 433MHz | F133 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F588 Dino | 01/2019-12/2022 | Huf/Beru 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F8 Tributo | 01/2019-12/2022 | 433MHz 282189 | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | FF | 01/2011-01/2020 | 433MHz | F151 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | FXX | 01/2005-12/2006 | 433MHz | F140 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | GTC4 Lusso | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | GrabSport Cabrio | 01/2007-12/2015 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | La Ferrari | 01/2013-12/2020 | 433MHz | F150 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Monza SP1/SP2 | 01/2019-12/2021 | 433MHz | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Portofino | 10/2017-12/2021 | F11001648001 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Portofino | 01/2018-12/2022 | 228887 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ferrari | Roma | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Roma | 01/2020-12/2022 | 433MHz 314818 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | SF90 Stralade | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Fiat | 1-Tonne Pickup | 01/2016-06/2019 | 433MHz | 4P00 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Fiat | 124 Spider | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 124 Spider | 08/2015-12/2021 | 433MHz | NF/J12F | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Fiat | 500 | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500 | 01/2014-12/2020 | 433MHz | 312 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500 | 01/2007-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500 | 01/2007-12/2013 | 433MHz | 312 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500C | 01/2014-06/2019 | 433MHz | 312 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500C | 01/2013-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500C | 01/2007-12/2013 | 433MHz | 312 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500L | 01/2012-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500L | 01/2007-12/2021 | 433MHz | 330 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500X | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500X | 01/2015-12/2015 | 433MHz | 334 | ● | ● | ● | O | 433MHz | Continental | ● | ● |
| Fiat | Albea | 10/2013-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Bravo | 01/2007-10/2016 | 433MHz | 198 | ● | ● | ○ | C | 433MHz | TRW | ● | ● |
| Fiat | Bravo | 01/2013-12/2014 | Clamp in 433MHz | 198 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Bravo | 01/2013-12/2014 | Snap in 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Croma | 01/2005-06/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Doblo | 01/2009-12/2021 | 433MHz | 223/263 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Doblo | 01/2010-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Doblo | 01/2020-12/2021 | 433MHz | X2/50 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Fiat | Ducato | 06/2014-06/2024 | 433MHz | X2/50 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Ducato | 01/2006-05/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Egea | 01/2015-12/2022 | Snap in 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Egea | 01/2015-12/2022 | Clamp in 433MHz | | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Fiorino | 10/2007-12/2014 | 433MHz | 225 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Fiorino | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | Fiorino | 01/2015-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Freemont | 01/2011-06/2014 | 433MHz | JF | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Freemont | 07/2014-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Fullback | 01/2016-12/2021 | 433MHz | 4P00/ KTOT | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Fiat | Grande Punto | 01/2006-05/2014 | 433MHz 53104671 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Fiat | Grande Punto | 01/2012-12/2015 | 433MHz | 199 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Idea | 01/2003-12/2012 | 433MHz | 350 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Fiat | Linea | 01/2007-12/2017 | 433MHz | 200 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Palio | 01/2007-12/2015 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Palio | 01/2011-12/2017 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Panda | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------|-----------------|-----------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Fiat | Panda | 11/2011-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Professional | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Fiat | Punto | 01/2005-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Punto | 09/2005-12/2018 | 433MHz | 199 | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| Fiat | Punto Evo | 01/2009-12/2012 | 433MHz | 199 | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Fiat | Punto Evo | 01/2009-12/2012 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | Qubo | 01/2007-12/2021 | 433MHz | 225 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Qubo | 01/2007-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | Scudo | 01/2016-06/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Scudo | 01/2006-10/2013 | 433MHz | G9 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Scudo | 11/2013-06/2019 | 433MHz | 3H/G9 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Sedici | 01/2014-12/2016 | 433MHz | YY2 | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Fiat | Strada | 01/2012-09/2021 | 433MHz | 178/326 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Talento | 01/2016-12/2022 | 433MHz | FJL/X82 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Tipo | 01/2015-12/2020 | Snap in 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Tipo | 01/2015-12/2020 | Clamp in 433MHz | | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Tipo | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Toro Pickup | 01/2016-12/2022 | 433MHz | 334 | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Fiat | Ulysse | 10/2005-06/2011 | 433MHz | UL0102/179/V1 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Fiat | Ulysse | 01/2002-09/2005 | 433MHz | FL166/179/V1 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Ford | B-MAX | 05/2012-12/2019 | 433MHz | B232 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | B-MAX | 05/2012-12/2016 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Bronco | 01/2021-12/2021 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | C-Max | 08/2010-12/2020 | 433MHz | C344 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | C-Max | 08/2010-12/2016 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | C-Max | 01/2014-12/2019 | 433MHz | CB7/CEU/C344 | ● | ● | ● | S/A | 433MHz | Schrader | ● | ● |
| Ford | E-Series | 01/2006-12/2018 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 06/2013-09/2014 | 433MHz | B515 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 01/2013-06/2019 | 433MHz | EV6T1A180CB | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 11/2017-12/2022 | 433MHz | CR6 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Edge | 06/2014-12/2014 | 433MHz | CD389/CD539 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Edge | 01/2007-12/2014 | U387 433MHz | U387 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Edge | 01/2015-06/2021 | 433MHz | CD389/CD539 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2015-12/2018 | 433MHz | C520 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 05/2012-12/2014 | 433MHz | C520 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2014-12/2019 | 433MHz | C520 (2) | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2011-12/2014 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2007-12/2008 | 433MHz | U222 | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 06/2003-12/2006 | 433MHz | U222 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2015-12/2020 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2009-06/2015 | 433MHz | U502 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | Explorer | 09/2015-12/2017 | 433MHz | U502 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2018-08/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 09/2019-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 09/2008-12/2010 | 433MHz | P415 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2015-12/2021 | 433MHz | P552 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2021-12/2022 | 433MHz | P702 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2011-12/2014 | 433MHz | P415 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2015-12/2018 | 433MHz | P415 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2010-12/2020 | 433MHz | P415 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | F-Series | 09/2008-12/2009 | 433MHz | P415 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Fiesta | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Fiesta | 01/2017-12/2022 | 433MHz | CE1 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Fiesta | 05/2014-06/2019 | 433MHz | CCN | ● | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Focus | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Focus | 12/2010-12/2018 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Focus | 01/2011-06/2019 | 433MHz EV6T1A180DB | CEW/CB8 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus | 05/2018-12/2019 | 433MHz | CGE | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Focus C-Max | 01/2014-06/2016 | 433MHz | CB7 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Focus IV | 09/2018-05/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus IV | 06/2019-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Focus RS | 08/2015-12/2018 | 433MHz | P3T/600A | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus ST | 05/2014-02/2018 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus ST | 03/2018-06/2021 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus (LCV) | 12/2010-12/2018 | 433MHz | C346 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | GT | 08/2017-12/2019 | 433MHz | CGX | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Ford | Galaxy | 01/2006-04/2015 | 433MHz | CD340 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Ford | Galaxy | 05/2015-06/2021 | 433MHz | CD390 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Grand C-MAX | 01/2014-12/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | KA | 01/2008-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ford | KA | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Ford | KA III | 01/2016-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | KA+ | 01/2016-06/2021 | 433MHz | KAF | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Kuga | 11/2012-12/2013 | 433MHz | C520 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Kuga | 01/2013-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Ford | Kuga | 01/2014-12/2019 | 433MHz | C520 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Kuga | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Mach E | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 09/2017-05/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 06/2019-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 10/2014-12/2017 | Snap in 433MHz | CD391 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 01/2007-12/2012 | Clamp in 433MHz | CD345 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Ford | Mondeo | 01/2013-06/2015 | Clamp in 433MHz | CD345 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Ford | Mustang | 01/2010-12/2014 | 433MHz | S197 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-----------------|-----------------|--------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | Mustang | 01/2015-12/2022 | 433MHz | S550 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2015-12/2015 | 433MHz | S197 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2007-12/2009 | 433MHz | S197 | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 09/2004-12/2006 | 433MHz | S197 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Mustang Mach-E | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | PUMA | 11/2019-12/2021 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2016-06/2021 | Lo Line 433MHz | P375 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2015-12/2022 | Hi Line 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 05/2014-12/2014 | 433MHz | P375 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2015-12/2015 | Lo Line 433MHz | P375 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | S-Max | 06/2019-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | S-Max | 05/2015-05/2019 | 433MHz | CD539/CD389 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | S-Max | 01/2006-04/2015 | 433MHz | CD340 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Ford | Tourneo Connect | 01/2013-05/2018 | 433MHz DR3V1A180DA | V408 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Connect | 05/2018-12/2022 | 433MHz F2GZ1A189B | V408 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Courier | 01/2014-06/2021 | 433MHz DR3V1A180BB | B460 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Custom | 09/2013-12/2019 | 433MHz | V362 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Custom | 01/2020-12/2022 | 433MHz | TTF | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 06/2013-12/2014 | 433MHz | V363 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 01/2015-12/2019 | 433MHz | V363 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Transit Chassis | 06/2013-05/2019 | 433MHz | V363 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Combi | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit Combi | 01/2013-12/2018 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2013-05/2018 | 433MHz EV6T1A180CB | V363 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2013-12/2018 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Transit Connect | 05/2018-12/2022 | 433MHz F2GZ1A189B | V408 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Courier | 01/2014-12/2021 | 433MHz EV6T1A180CB | B460 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Courier | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Transit Custom | 09/2013-12/2019 | 433MHz | V363 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Custom | 01/2020-12/2022 | 433MHz | TTS | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit LCV | 01/2013-12/2019 | 433MHz | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Vignale Mondeo | 01/2015-12/2019 | 433MHz | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Vignale S-Max | 01/2015-12/2020 | 433MHz | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Foton | Sauvana | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | TTE | ● | ● |
| Foton | Tunland | 01/2011-12/2021 | 433MHz | | ● | ● | ○ | C | 433MHz | TTE | ● | ● |
| GMC | Savana | 01/2009-12/2012 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Savana | 07/2007-12/2008 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Savana | 01/2002-06/2007 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|---------------------|-----------------|--------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| GMC | Sierra | 01/2015-12/2018 | 433MHz | K2XG2 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2014-12/2014 | 433MHz | K2XG2 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2013-12/2013 | 433MHz | K2XG2 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 07/2009-12/2017 | 433MHz | GMT902 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 06/2006-06/2009 | 433MHz | GMT902 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2005-12/2006 | 433MHz | GMT922 (2) | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2015-12/2019 | 433MHz | K2UG (2) / GMT922 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2014-12/2014 | 433MHz | K2UG / GMT922 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2009-12/2013 | 433MHz | GMT922 (2) | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2007-12/2008 | 433MHz | GMT922 (2) | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Geely | Atlas | 09/2019-12/2020 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Atlas | 01/2015-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | Atlas Pro | 09/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Atlas Pro | 09/2020-12/2021 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Atlas X | 01/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | BINRUI | 04/2019-12/2020 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | BINRUI | 01/2018-12/2019 | SAT 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | BINRUI | 01/2018-03/2019 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | BINYUE | 07/2018-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | BINYUE | 01/2019-12/2020 | SAT 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | BINYUE Pro | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | BINYUE QINGHUN | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Coolray | 09/2019-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | EC7 | 01/2013-12/2014 | 433MHz 6703202 | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | EC7 | 01/2012-12/2018 | TTE 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | EC7 | 01/2009-12/2012 | 433MHz 6703202 | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | EC7 | 01/2009-12/2012 | 433MHz 6701004 | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | EC8 | 01/2011-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Whetron | ● | ● |
| Geely | EMGRAND | 06/2019-12/2020 | SAT 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | EMGRAND | 01/2017-05/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | EMGRAND | 01/2017-05/2019 | 433MHz 01734809 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | EMGRAND EV | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | EMGRAND EV | 01/2015-06/2019 | TTE 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | EMGRAND EV Pro | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND EV450/EV500 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Geely | EMGRAND GL | 01/2018-06/2019 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND GL | 07/2019-12/2020 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND GL | 09/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | EMGRAND GS | 06/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | EMGRAND GS | 01/2015-05/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | EMGRAND HEV | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Geely | EMGRAND PHEV | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | EMGRAND RS | 08/2015-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | FY11 | 07/2021-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | FY11 | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GC9 | 01/2015-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | GE | 07/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | GE | 01/2015-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | GE11 A | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GE11 A1 | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GE11 C | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GSE | 01/2018-12/2019 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GX7 | 01/2014-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | GX7 | 01/2014-12/2015 | Lear 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | GX9 | 01/2015-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | ICON | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | SC6 | 01/2014-12/2017 | TTE 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | SX7 | 01/2013-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | SX7 | 01/2013-12/2014 | TTE 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | VF11 | 01/2019-12/2019 | G5 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | VF11 | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | VX11 | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Yuanjing | 07/2019-12/2020 | 433MHz New | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Yuanjing | 01/2018-06/2019 | 433MHz New | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Yuanjing S1 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Geely | Yuanjing S1 | 06/2019-12/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Lear | ● | ● |
| Geely | Yuanjing X3 | 06/2019-12/2020 | G6 MT 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Yuanjing X3 | 12/2017-08/2020 | G5 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Yuanjing X3 | 06/2019-12/2020 | G6 CVT 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Geely | Yuanjing X3 | 01/2017-11/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | Yuanjing X6 | 01/2016-12/2020 | 433MHz (10170 40454) | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Yuanjing X6 | 01/2020-12/2020 | 433MHz CVT | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Yuanjing X6 | 01/2015-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | Yuanjing X6 AT | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Yuanjing X6 Pro | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| GreatWall | M4 | 01/2015-12/2017 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| GreatWall | M4 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| GreatWall | P8 | 08/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | PA0 | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| GreatWall | Steed | 06/2014-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | Steed | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | SAT | ● | ● |
| GreatWall | Tracker | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | SAT | ● | ● |
| GreatWall | Tracker | 01/2015-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | VV5 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | VV6 | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | VV7 | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| GreatWall | VV7 | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Voleex C20 | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| GreatWall | Voleex C20R | 01/2014-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C30 | 01/2015-12/2017 | SAT 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C30 | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C30 | 01/2014-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Voleex C30 EV | 01/2018-12/2020 | OB 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Voleex C30 EV | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Voleex C50 | 01/2011-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C50 | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 5 | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 5 | 01/2011-12/2015 | 433MHz | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 6 | 01/2015-11/2018 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 6 | 01/2012-12/2015 | SAT 433MHz | | ● | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 7 | 06/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| HSV | ClubSport GXP | 01/2010-12/2010 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| HSV | GTS | 01/2007-12/2012 | 433MHz | HT0078 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| HSV | Grange | 01/2007-12/2012 | 433MHz | HR0078 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| HSV | Maloo GXP | 01/2010-12/2010 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| HSV | R8 | 01/2007-12/2012 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| HSV | Senator | 01/2007-12/2012 | 433MHz | HE0078 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| HaiMa | Family | 01/2012-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | Freema | 01/2012-12/2016 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | Haima 7 | 01/2012-12/2013 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | M3 | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| HaiMa | M6 | 06/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| HaiMa | S5 | 01/2014-06/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | Steel Mate | ● | ● |
| HaiMa | S7 | 01/2013-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| Haval | Dargo | 09/2020-12/2021 | SCH 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Haval | Dargo | 09/2020-12/2021 | SAT 433MHz | | ● | ● | ○ | O/A | 433MHz | SAT | ● | ● |
| Haval | F5 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | F7 | 11/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | F7 | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Haval | F7X | 04/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H1 | 01/2014-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H2 | 01/2014-05/2018 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H2 | 06/2018-12/2021 | 433MHz 3641100XKU00 B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H2s NEW | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H4 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H5 | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H5 | 01/2010-12/2016 | 433MHz | | ● | ● | ○ | S | 433MHz | SAT | ● | ● |
| Haval | H5 Classics | 01/2015-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|------------|-----------------|-----------------------------|----------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Haval | H6 | 01/2011-12/2015 | 433MHz SAT | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 | 01/2016-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 Coupe | 01/2015-05/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 Coupe | 06/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 NEW | 01/2017-12/2021 | 433MHz | CC6472RM CC6464RM | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H7 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H7L | 06/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H7L | 01/2017-12/2020 | 433MHz 3641100XKU00 B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H8 | 01/2013-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H9 | 09/2020-12/2021 | SCH 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Haval | H9 | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Jolion | 01/2021-12/2021 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Jolion | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Haval | M2 | 01/2014-12/2015 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Haval | M6 | 07/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | M6 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Holden | Colorado | 01/2013-12/2017 | 433MHz | GMI700 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | WM Caprice | 01/2007-12/2012 | 433MHz | WM | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Honda | Accord | 01/2015-12/2015 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Accord | 01/2009-12/2013 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Accord | 01/2014-12/2019 | Direct 433MHz | 2GA/2GB/QE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | CR-V | 01/2015-12/2021 | Direct 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | CR-V | 01/2010-12/2018 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | CR-Z | 01/2010-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Civic | 01/2009-12/2012 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Civic | 01/2013-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Civic | 01/2015-12/2020 | Direct 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Clarity | 01/2016-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Crosstour | 01/2012-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | HR-V | 11/2014-06/2021 | Direct 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | HR-V | 09/2014-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Honda e | 01/2019-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Insight | 06/2009-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Jazz | 01/2014-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Jazz | 01/2014-12/2020 | Direct 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | NSX | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | NSX | 01/2016-06/2021 | Direct 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Passport | 01/2019-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hummer | H2 | 07/2006-12/2007 | 433MHz | H28 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Hummer | H2 | 01/2008-12/2008 | 433MHz | H28 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hummer | H2 | 01/2002-06/2006 | 433MHz | H28 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Hummer | H3 | 01/2005-12/2006 | 433MHz | H38/GMT345 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Hummer | H3 | 01/2007-12/2012 | 433MHz | H38/GMT345 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Hyundai | Accent | 04/2011-12/2021 | Hi Line 433MHz | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 01/2014-06/2020 | Lo Line 433MHz | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Azera | 09/2014-02/2017 | 433MHz | HG | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Azera | 03/2017-12/2019 | 433MHz | IG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Azera | 01/2011-08/2014 | 433MHz | HG | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Bayon | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | C-Green | 01/2016-06/2019 | 433MHz | AE | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| Hyundai | Centennial | 01/2013-12/2018 | 433MHz | VI New | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Centennial | 07/2009-12/2013 | 433MHz | VI Old | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Creta | 01/2016-12/2020 | Russia 433MHz | GSB/GSR | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 11/2015-12/2021 | 433MHz | GSB/GSR | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 01/2016-12/2019 | Other 433MHz | GS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Creta | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | E-Niro | 01/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Elantra | 01/2008-12/2012 | 433MHz | FD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 01/2012-12/2013 | 433MHz | MD | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Elantra | 01/2015-12/2020 | 433MHz | AD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 07/2020-12/2022 | 433MHz 52940L1100 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 01/2014-12/2018 | 433MHz | MD/UD | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Equus | 01/2008-12/2013 | 433MHz | VI Old | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Equus | 01/2013-12/2016 | 433MHz | VI New | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis | 01/2007-12/2014 | 433MHz | BH | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Genesis | 01/2013-12/2017 | 433MHz | DH | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis Coupe | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G70 | 01/2017-12/2017 | 433MHz | IK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G70 | 01/2018-12/2021 | 433MHz | IK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G80 | 07/2016-12/2022 | 433MHz | DH | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G90 | 01/2017-12/2022 | 433MHz | HI | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G90 | 01/2016-12/2016 | 433MHz | HI | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV70 | 12/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV80 | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Grand SantaFe | 04/2013-12/2019 | DM 433MHz | NC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Grand SantaFe | 01/2019-12/2020 | 433MHz 52933C1100 | DM | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Grandeur | 01/2017-12/2020 | 433MHz | IG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Grandeur | 06/2011-12/2015 | HG 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Grandeur | 01/2011-12/2017 | DM 433MHz | HG | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Grandeur | 01/2018-12/2019 | 433MHz | IG LAMBDA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Grandeur | 01/2015-12/2017 | Hybrid 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | H-1 | 06/2021-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | H-1 | 03/2014-06/2021 | 433MHz | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | H-350 | 06/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Hyundai | H100 | 01/2014-12/2022 | 433MHz | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | H300 | 01/2010-12/2013 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Hyundai | H300 | 01/2014-06/2021 | 433MHz | LU/AU | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq | 01/2016-12/2021 | 433MHz | AE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Kauai | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Kona | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Continental | ● | ● |
| Hyundai | Kona | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Continental | ● | ● |
| Hyundai | Nexo | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Nexo | 04/2018-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Niro | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Hyundai | Palisade | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Palisade | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Porter | 01/2014-12/2020 | HR 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 04/2017-12/2018 | 433MHz | DM/DMI | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 01/2006-12/2008 | 433MHz | CM | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Hyundai | Santa Fe | 04/2013-03/2017 | 433MHz | DM/DMI | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 01/2009-05/2012 | 433MHz | CM | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Hyundai | Santa Fe | 03/2018-12/2022 | 433MHz | TM/TMA | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 06/2012-03/2013 | 433MHz | DM/NC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Solaris | 01/2014-12/2019 | 433MHz | HC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Solaris | 01/2011-03/2017 | 433MHz | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 05/2019-12/2020 | 433MHz 52940L1100 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 04/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata | 04/2014-04/2019 | Hi Line 433MHz | LF/LFA | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata | 01/2014-02/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Sonata Hybrid | 08/2017-06/2020 | Hi Line 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata Hybrid | 08/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Starex | 03/2011-03/2021 | 433MHz | A1 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Hyundai | Staria | 03/2021-12/2027 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Hyundai | Sub-Compact SUV | 01/2015-06/2019 | 433MHz | IB | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Hyundai | Tucson | 01/2010-05/2015 | 433MHz | LM | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Tucson | 10/2020-12/2022 | 433MHz | NX4 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2016-09/2020 | 433MHz | TL/TLE | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 06/2015-08/2018 | 433MHz | LM | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2015-12/2015 | 433MHz | TL/TLE | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 11/2013-09/2015 | Lo line 433MHz | EL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Tucson | 07/2013-06/2015 | Hi line 433MHz | EL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|------------------|--------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Veloster | 01/2019-12/2020 | FS 433MHz | FS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Veloster | 03/2011-06/2019 | 433MHz | FS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Venue | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Veracruz | 01/2009-12/2013 | 433MHz | EN | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Hyundai | i10 | 01/2020-12/2020 | Indirect | LA | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Hyundai | i10 | 11/2013-06/2020 | 433MHz | IA | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | i10 | 10/2007-10/2013 | 433MHz | IA/PA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i20 | 01/2013-12/2016 | 433MHz | PB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i20 | 01/2020-12/2020 | 433MHz | BC | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i20 | 01/2008-12/2012 | 433MHz | PB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i20 | 10/2014-12/2021 | 433MHz | GB | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i20n | 10/2021-12/2022 | 433MHz | BC | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i30 | 08/2016-12/2022 | 433MHz | PD/Pde | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 12/2011-12/2017 | 433MHz | Gde | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 05/2007-03/2014 | 433MHz | FD/Fde | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 01/2017-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Hyundai | i30 | 04/2014-12/2018 | 433MHz | GD | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | i40 | 01/2017-12/2019 | 433MHz | IF | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i40 | 04/2014-12/2020 | 433MHz | VF | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Hyundai | i40 | 01/2011-03/2014 | 433MHz | VF | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | i800 | 01/2013-02/2014 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Hyundai | i800 | 06/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Hyundai | i800 | 03/2014-06/2021 | 433MHz | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | iLoad | 01/2014-12/2020 | TQ 433MHz | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | iMax | 01/2015-12/2016 | 433MHz | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | ix20 | 04/2017-12/2021 | 433MHz | JC/IX5 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | ix20 | 10/2013-03/2017 | 433MHz | JC/IX5 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | ix20 | 01/2010-09/2013 | 433MHz | JC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | ix25 | 01/2017-12/2019 | 433MHz | OS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | ix35 | 01/2010-08/2013 | 433MHz | LM/EL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 01/2013-12/2020 | FUEL CELL 433MHz | EL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 09/2013-12/2015 | Hi Line 433MHz | EL | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 09/2013-12/2016 | 433MHz | LM | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 01/2017-09/2017 | FUEL CELL 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 10/2015-06/2020 | 433MHz | TL/TLE | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | ix35 | 09/2013-12/2019 | Lo Line 433MHz | LMC/EL/ELH/LM FCEV | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | ix55 | 01/2007-12/2013 | EN 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Hyundai | ix55 | 10/2008-12/2019 | 433MHz | EN | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | EX Series | 01/2007-03/2014 | 433MHz | P53B/J50 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | FX Series | 03/2008-04/2015 | 433MHz | P53C/S51 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | G Series | 01/2010-12/2014 | 433MHz | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Infiniti | G Series | 01/2006-02/2014 | 433MHz | CV36/G312/L53A | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | JX35 | 09/2012-07/2020 | 433MHz | L50 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|------------|-----------------|--------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Infiniti | M Series | 12/2009-04/2016 | 433MHz | M312/Y51 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | M Series | 01/2008-12/2013 | 433MHz | L53E | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | Q30 | 01/2015-12/2021 | 433MHz | GD1A/H15 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Infiniti | Q50 | 01/2013-06/2021 | 433MHz | L53H/D53H/V37 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | Q60 | 07/2013-06/2016 | 433MHz | L53A/CV36 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q60 | 01/2013-12/2022 | 433MHz Continental | L53H/D53H | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | Q60 Coupe | 06/2013-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | Q70 | 10/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | Q70 | 01/2014-11/2015 | 433MHz | M312/Y51 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q70 | 01/2013-12/2021 | 433MHz | L53E | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX30 | 09/2015-12/2022 | 433MHz | GD1A/H15 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Infiniti | QX40 | 04/2017-06/2019 | 433MHz | PD2A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX50 | 11/2015-12/2019 | VDO 433MHz | P53B(2) | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX50 | 01/2014-12/2019 | PAC 433MHz | P53B/J50 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX50 | 01/2014-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | QX56 | 01/2010-12/2012 | 433MHz | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Infiniti | QX60 | 11/2012-12/2019 | 433MHz | P42J | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX70 | 01/2016-12/2019 | VDO 433MHz | P53J | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX70 | 01/2014-06/2020 | PAC 433MHz | P53C/S51 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX70 | 07/2013-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | QX80 | 01/2010-09/2016 | 433MHz | JA60 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX80 | 01/2013-12/2022 | 433MHz | Z62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Isuzu | D-Max | 01/2007-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Isuzu | D-Max | 06/2016-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | | ● | ● |
| Isuzu | D-Max | 09/2020-12/2022 | SCH 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Isuzu | MU-X | 11/2016-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Iveco | Daily | 02/2019-12/2022 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| JAC | IEV A50 | 08/2019-06/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | IEV S4 | 09/2019-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | Iev7s | 01/2017-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | JAC | ● | ● |
| JAC | J4 | 01/2016-12/2021 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | J6 | 01/2011-12/2016 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | J6 A30 | 01/2012-12/2012 | 433MHz | | ○ | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | J6 A30 | 01/2015-12/2016 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | J6 B15 | 01/2012-12/2016 | 433MHz | | ○ | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | Refine A60 | 01/2015-12/2017 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine M2 | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine M4 | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine M5 | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine M6 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine R3 | 01/2018-06/2020 | SAT 433MHz | | ● | ● | ○ | S | 433MHz | SAT | ● | ● |
| JAC | Refine R3 | 01/2018-06/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine S2 | 01/2015-12/2020 | Steel 433MHz | | ● | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | Refine S2 | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine S3 | 01/2014-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-----------|-----------------|---------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| JAC | Refine S4 | 08/2019-12/2020 | 433Mhz | | ● | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| JAC | Refine S5 | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine S7 | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | T6 | 01/2015-12/2020 | SCH 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | T8 | 04/2020-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| JAC | iEV6E | 01/2018-07/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | JAC | ● | ● |
| JETOUR | X70 | 06/2018-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | Baolong | ● | ● |
| JETOUR | X70M | 03/2020-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | Baolong | ● | ● |
| Jaguar | E-Pace | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 01/2015-12/2022 | 433MHz | X761 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2012-12/2020 | 433MHz | F52 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2017-06/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2016-06/2021 | 433MHz | X152 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2012-12/2015 | 433MHz | X152 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 01/2018-12/2022 | KR5S18005202 0A 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 01/2017-06/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | RD-7 | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | S-Type | 10/1998-08/2011 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | X-Type | 01/2007-12/2015 | 433MHz | X400 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 01/2015-03/2015 | 433MHz | X760 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 01/2015-06/2022 | GX631A159AA 433MHz | X760 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 01/2007-12/2015 | 433MHz | X250 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 07/2014-05/2015 | 433MHz | X260 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 06/2015-12/2022 | 433MHz | X260 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2010-12/2015 | 433MHz | X351 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 10/2002-12/2009 | 433MHz | X350 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2010-12/2020 | KR5S18005202 0A 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2016-12/2022 | 433MHz | X351 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 09/2005-12/2015 | 433MHz | X150 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XKR | 01/2006-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | B-CUV | 10/2014-12/2016 | 433MHz | 520 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | C-CUV | 01/2016-06/2019 | 433MHz | MP | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Jeep | Cherokee | 01/2005-12/2013 | 433MHz 56029359AC | KK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Cherokee | 01/2018-12/2018 | 433MHz 68324960AA | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2019-12/2022 | 433MHz 68324960AB | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2018-06/2020 | 433MHz | KL | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2017-12/2017 | 433MHz | KL | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2014-12/2016 | 433MHz | KL | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2002-12/2004 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Commander | 01/2006-12/2010 | 433MHz | XK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Compass | 09/2014-12/2017 | 433MHz | MK49 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2018-12/2022 | 433MHz | 551 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jeep | Compass | 01/2017-12/2017 | 433MHz | 551 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 05/2006-08/2014 | 433MHz | MK49 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2018-01/2023 | 433MHz | MP/MX | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2017-12/2017 | 433MHz | MP/MX | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | D-CUV | 05/2013-12/2016 | 433MHz | KL | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Gladiator | 11/2019-12/2022 | MRXAG4WA5 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Gladiator | 07/2021-12/2022 | Conti 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2005-05/2006 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 04/2021-12/2022 | Conti 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2018-06/2021 | 433MHz | WK | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2016-12/2017 | 433MHz | WK | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2014-12/2015 | 433MHz | WK74 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2012-12/2013 | 433MHz | WK74 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2011-12/2011 | 433MHz | WK74 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 06/2006-12/2010 | 433MHz | WH | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2016-12/2022 | 433MHz 68252493AB | WK | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2001-12/2004 | 433MHz | WK/WJ | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Jeep | Liberty | 01/2010-12/2015 | 433MHz | Li0103 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Liberty | 01/2005-12/2009 | 433MHz | | ● | ● | ○ | C | 433MHz | Continental | ● | ● |
| Jeep | Patriot | 12/2006-12/2017 | 433MHz | MK74 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Renegade | 01/2018-12/2021 | 433MHz | BU/520 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2016-12/2017 | 433MHz 68252493AB | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2014-12/2017 | 433MHz | BU/520 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2018-12/2022 | 433MHz 68193586AC | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Wagoneer | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Wrangler | 06/2006-08/2010 | 433MHz | JK72 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 07/2021-12/2022 | Conti 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Wrangler | 01/2018-06/2021 | 433MHz | JL | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2018-12/2019 | 433MHz | JK72 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2014-12/2017 | 433MHz | JL | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 09/2010-12/2017 | 433MHz | JK72 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| KIA | C-CUV EV | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | Cadenza | 01/2011-07/2016 | 433MHz | VG | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Cadenza | 01/2016-06/2020 | 52933D9100 433MHz | YG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Cadenza | 01/2017-12/2021 | 529333N100 433MHz | YG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Carens | 01/2006-12/2020 | 433MHz | RP/UN | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Carnival | 01/2016-12/2018 | 433MHz | YP/VQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Carnival | 01/2019-12/2019 | 433MHz | YP | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Carnival | 03/2021-12/2022 | 52940L1100 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Carnival | 01/2014-12/2018 | Sedan 433MHz | YP | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Ceed | 01/2006-09/2012 | 433MHz | ED | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|---------------|-----------------|----------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | Ceed | 01/2018-12/2021 | 433MHz | CD | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| KIA | Ceed | 03/2012-06/2018 | 433MHz | JD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Ceed SW | 05/2018-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Ceed SW | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| KIA | Ceed SW | 01/2006-08/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Ceed SW | 09/2012-04/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Cerato | 01/2015-12/2016 | BD 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Cerato | 01/2016-12/2018 | YD 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Cerato | 01/2019-12/2020 | YD 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Cerato | 02/2009-12/2014 | TD 433MHz | | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| KIA | E-Niro | 10/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | E-Soul | 04/2019-12/2020 | 433MHz | SK3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | EV6 | 03/2021-12/2027 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | K2700 | 06/2014-12/2020 | 433MHz | PU | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K3 | 01/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | K5 | 01/2020-12/2020 | 433MHz | DL3 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Magentis | 10/2010-12/2015 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| KIA | Mohave | 09/2014-12/2019 | Lo line 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Mohave | 09/2014-12/2019 | Hi line 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Mohave | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Mohave | 01/2008-08/2014 | 433MHz | | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| KIA | Morning | 01/2017-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| KIA | Morning | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Niro | 01/2016-12/2021 | 433MHz | DE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Optima | 01/2020-12/2020 | 433MHz | DK3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Optima | 09/2015-12/2022 | 433MHz | JF/JFA | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Optima | 08/2013-12/2016 | 433MHz | TF/TF HEV | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Optima | 06/2010-07/2013 | 433MHz | TF/TF HEV | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 01/2016-12/2019 | 433MHz | JF HEV/PHEV | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 01/2014-12/2015 | 433MHz | TF HEV | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 06/2012-12/2013 | 433MHz | TF HEV | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Picanto | 01/2011-12/2017 | TA 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Picanto | 01/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| KIA | Picanto | 01/2016-12/2022 | 433MHz | TA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Pro Ceed | 05/2018-06/2021 | 433MHz | CD | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| KIA | Pro Ceed | 03/2012-06/2018 | 433MHz | JD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Pro Ceed | 01/2008-08/2012 | 433MHz | ED | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Quoris | 06/2012-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Rio | 01/2017-12/2021 | 433MHz | YB | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| KIA | Rio | 01/2011-06/2014 | 433MHz | UB | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Rio | 05/2014-06/2020 | Hi line 433MHz | UB | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| KIA | Rio | 06/2014-12/2020 | Lo line 433MHz | UB | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| KIA | Rio | 12/2016-06/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|---------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | Sedona | 01/2015-12/2020 | 433MHz | YP | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Seltos | 06/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sonet | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Sorento | 10/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2017-12/2023 | 433MHz 52933D4100 | UMA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2009-07/2012 | 433MHz | XM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 07/2012-12/2015 | 433MHz | UM/XM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2016-06/2020 | 433MHz | UM/XM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Soul | 06/2008-10/2013 | 433MHz | AM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Soul | 10/2013-12/2019 | 433MHz | PS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Soul | 01/2019-12/2022 | 433MHz | SK3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Soul EV | 06/2014-12/2019 | 433MHz | PS EV | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Soul Electric | 06/2014-12/2019 | 433MHz | SK3 EV | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Sportage | 10/2013-01/2016 | 433MHz | SL | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| KIA | Sportage | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Sportage | 11/2015-06/2021 | 433MHz | QL/QLE | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Sportage | 01/2014-12/2015 | Hi Line 433MHz | SL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Sportage | 01/2010-01/2014 | Hi Line 433MHz | SL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Sportage | 01/2010-12/2013 | Lo Line 433MHz | SL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Stinger | 01/2018-12/2022 | 433MHz | CK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Stinger | 06/2017-12/2017 | 433MHz | CK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Stonic | 11/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Stonic | 01/2017-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| KIA | Venga | 06/2009-04/2014 | 433MHz | YN | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Venga | 05/2014-06/2020 | 433MHz | YN | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | XCeed | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | XCeed | 01/2020-06/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| LYNK_CO | 01 | 01/2020-12/2021 | SCH 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| LYNK_CO | 02 | 01/2020-12/2021 | SCH 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Lada | 4x4 | 01/2014-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Lada | Granta | 09/2012-06/2016 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Lada | Granta | 04/2014-12/2021 | 407004CBOA 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Lada | Kalina | 05/2013-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Lada | Largus | 01/2015-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Lada | Priora | 01/2014-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Lada | Vesta | 02/2017-12/2022 | Schrader 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Lada | Vesta | 01/2015-12/2022 | VDO 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Lada | Vesta | 09/2015-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Lada | Xray | 01/2015-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Lamborghini | Aventador | 01/2011-12/2022 | 433MHz | LB834 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Centenario | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Few Off | 01/2017-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|-----------------|-----------------|---------------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lamborghini | Gallardo | 01/2003-06/2018 | 433MHz | LB714/LB724 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Huracan | 01/2014-06/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | LP640 | 06/2007-01/2010 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Murcielago | 01/2002-12/2015 | 433MHz | LB824 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | One off | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Reventon | 01/2007-12/2010 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Sian | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Urus | 01/2018-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lancia | Delta | 06/2014-12/2020 | 433MHz | PK | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lancia | Delta | 01/2008-05/2014 | 433MHz | 844 | ● | ● | ○ | C | 433MHz | TRW | ● | ● |
| Lancia | Flavia | 01/2014-12/2016 | 433MHz | UF | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Lancia | Flavia | 01/2012-12/2014 | 433MHz | JS27 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Lancia | Flavia | 01/2010-12/2011 | 433MHz | JS27 | ● | ● | ● | O | 433MHz | Continental | ● | ● |
| Lancia | Musa | 01/2004-12/2014 | 433MHz | 848 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Lancia | Phedra | 01/2002-12/2012 | Conti 433MHz | 179 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Lancia | Phedra | 01/2002-09/2005 | SCH 433MHz | 179 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Lancia | Thema | 01/2011-12/2018 | 433MHz | LX | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Lancia | Voyager | 11/2015-12/2017 | 433MHz | RU/RA | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Lancia | Voyager | 01/2011-10/2015 | 433MHz | RT/RU | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Lancia | Voyager | 01/2007-12/2010 | 433MHz | RT | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Lancia | Ypsilon | 01/2011-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Lancia | Ypsilon | 01/2011-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Land Rover | Defender | 01/2019-06/2023 | 433MHz LR070840 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 01/2019-12/2022 | 433MHz LR066378 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 01/1997-12/2019 | KR5S18005202 0A 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2017-06/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 07/2004-12/2016 | KR5S18005202 0A 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2004-01/2017 | KR5S18005202 0 433MHz | Di4 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 11/2004-11/2009 | KR5S12278000 2 433MHz | Di092 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 12/2009-12/2014 | 433MHz | Di4 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2014-12/2022 | 433MHz | L550 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 07/2014-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery5 | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery5 | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | FreeLander | 01/2006-06/2022 | 433MHz | Fr132 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2005-12/2009 | 433MHz | L322 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2013-01/2017 | 433MHz | D5, D6, Ra5 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2010-12/2015 | 433MHz | L322 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2002-12/2004 | 433MHz | L30 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Range Rover | 06/2015-12/2022 | 433MHz | D6, Ra5 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------------|-----------------|---------------------------|-----------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover Evoque | 10/2015-06/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 03/2011-12/2022 | FW931A159AB 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 01/2011-12/2019 | BH521A159AA 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2011-12/2014 | 433MHz | Ev52 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Grand Evoque | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 06/2015-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 06/2014-12/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 05/2010-05/2015 | KR5S18005202 0A 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2005-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-08/2013 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 01/2017-06/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2016-12/2022 | LR070840 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2014-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2005-12/2013 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Lexus | C-CUV | 11/2014-12/2016 | 433MHz | 600A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | CT Series | 12/2010-12/2021 | 433MHz | 080A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 01/2006-05/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 06/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 06/2012-05/2018 | 433MHz | 980L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GS Series | 01/2005-12/2011 | 433MHz | GS32 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GS Series | 01/2012-12/2021 | 433MHz | 920L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GS430 | 01/2006-12/2006 | 433MHz PMV1019 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GX Series | 08/2013-08/2019 | 433MHz | J150 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GX Series | 01/2006-12/2009 | 433MHz | J120 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GX Series | 09/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | IS Series | 04/2013-12/2021 | 433MHz | 030L/400A/7 20A/ XE30 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | IS Series | 01/2006-03/2013 | 433MHz | XE20 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LC Series | 05/2017-12/2021 | Hi Line 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LC Series | 05/2017-12/2021 | Lo Line 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LC Series | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LFA | 06/2014-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LFA | 01/2010-12/2012 | 433MHz | LFA | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 10/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lexus | LS Series | 10/2012-09/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 08/2006-09/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LX Series | 10/2015-12/2021 | PMVC215 433MHz | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LX Series | 06/2012-12/2022 | PMVC210 433MHz | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LX Series | 01/2005-12/2010 | 433MHz | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | NX Series | 01/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | NX Series | 01/2014-12/2022 | 433MHz | 600A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RC Series | 01/2014-12/2022 | 433MHz | XC1/720A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RX Series | 01/2013-10/2015 | 433MHz | 640L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RX Series | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RX Series | 11/2015-12/2021 | C215 433MHz | 740A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | SC Series | 01/2001-12/2010 | 433MHz | UZZ40 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | UX Series | 01/2020-12/2021 | PMV-E100 433MHz | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | UX Series | 01/2018-12/2021 | 433MHz | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lifan | 820 | 01/2015-12/2016 | 433MHz | | ○ | ● | ○ | S | 433MHz | LiFan | ● | ● |
| Lifan | MaiWei | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | LiFan | ● | ● |
| Lifan | Maiwei | 01/2018-12/2020 | 433MHz SCA3638200 | | ● | ● | ○ | 0 | 433MHz | LiFan | ● | ● |
| Lifan | X50 | 01/2014-12/2015 | 433MHz | | ○ | ● | ○ | S | 433MHz | LiFan | ● | ● |
| Lifan | X70 | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | LiFan | ● | ● |
| Lifan | X70 | 01/2017-12/2020 | 433MHz SCA3638200 | | ○ | ● | ○ | C | 433MHz | LiFan | ● | ● |
| Lincoln | MKX | 02/2012-06/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2015-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2016-12/2022 | 433MHz | FA0114 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2011-12/2014 | 433MHz | FA0114 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lotus | 3 Eleven | 01/2015-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | 3-Eleven | 06/2017-12/2021 | A132G6017F 433MHz | | ○ | ● | ○ | A | 433MHz | LDL Technology | ● | ● |
| Lotus | Elan | 01/2018-12/2018 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Lotus | Elise | 09/2000-05/2021 | 433MHz | Monza | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Evija | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | LDL Technology | ● | ● |
| Lotus | Evora | 06/2009-12/2021 | 433MHz | Eagle | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Evora | 07/2015-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | LDL Technology | ● | ● |
| Lotus | Exige | 02/2017-12/2021 | A132G6017F 433MHz | | ○ | ● | ○ | A | 433MHz | LDL Technology | ● | ● |
| Lotus | Exige | 09/2000-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Luxgen | 5 | 07/2013-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Luxgen | M7 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Luxgen | S3 | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Luxgen | S5 | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Luxgen | U5 | 01/2016-06/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | SAT | ● | ● |
| Luxgen | U6 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Luxgen | U7 | 01/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Luxgen | V7 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | TTE | ● | ● |
| MAN | TGE | 01/2014-12/2016 | Continental 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| MAN | TGE | 01/2017-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| MAXUS | E-Deliver 3 | 01/2020-06/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Dias | ● | ● |
| MAXUS | E-Deliver 9 | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Dias | ● | ● |
| MAXUS | V80 | 01/2015-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| MG | EZS | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| MG | GS | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| MG | GS | 09/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | HS | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| MG | HS | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| MG | MG3 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| MG | MG3 | 09/2013-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | MG5 EV | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| MG | MG6 | 01/2012-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | MG6 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| MG | MG6 | 01/2021-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| MG | ZS | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| Mahindra | B-CUV | 01/2016-01/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Bolero | 09/2003-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Genio | 01/2014-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Goa | 01/2014-12/2022 | 433MHz | W105 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | KUV100 | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | NC | 06/2014-12/2018 | 433MHz | CL/MM | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | NUVOSPORT | 01/2017-01/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Quanto | 01/2016-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Scorpio | 06/2014-12/2019 | 433MHz | U202 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Thar | 01/2014-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | XUV500 | 01/2013-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | XYLO | 01/2017-01/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | e20 | 01/2014-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | 4200 | 01/2001-12/2007 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | 4200 GT/Coupe | 01/2002-12/2007 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Maserati | Alfieri | 01/2016-12/2021 | 433MHz | M165 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Coupe | 07/2009-12/2013 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Coupe | 01/2002-06/2009 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Coupe | 01/2001-12/2007 | 433MHz | M138 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Maserati | GT Coupe | 01/2002-12/2013 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GT Coupe | 01/2014-12/2020 | 433MHz | M145 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | GT Coupe | 03/2014-12/2020 | 433MHz | M138 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Ghibli | 01/2013-12/2020 | 433MHz | M156/M157 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Ghibli | 10/2018-12/2021 | 433MHz | M156D | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Maserati | GranCabrio | 07/2015-12/2017 | SCH 433MHz | M147 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | GranCabrio | 01/2008-08/2009 | 433MHz | M147 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranCabrio | 09/2009-12/2022 | Huf 433MHz | M147 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------------|-----------------|------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Maserati | GranTurismo | 01/2007-08/2010 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 09/2010-12/2013 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 01/2014-01/2022 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | GranTurismo Sport | 01/2013-07/2017 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo Sport | 08/2017-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Levante | 01/2016-12/2019 | 433MHz | M161 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Levante | 01/2020-12/2021 | 433MHz | M161 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Maserati | Levante | 04/2015-12/2022 | 433MHz | WM | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Quattroporte | 01/2013-12/2022 | 433MHz | M156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Quattroporte | 10/2018-12/2020 | Conti 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Maserati | Quattroporte | 01/2011-12/2015 | 433MHz | M139 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 01/2010-12/2010 | 433MHz | M139 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 04/2003-12/2009 | 433MHz | M139 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maybach | GLS SUV | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maybach | Landulet | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Maybach | Landulet | 10/2008-12/2014 | 433MHz | Ma009-127 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 57 | 02/2002-12/2013 | 433MHz | Ma007 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 62 | 02/2002-12/2013 | 433MHz | Ma007 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | S Series | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Mazda | B Series LCV | 05/2011-12/2018 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mazda | B-Hatch Xev | 09/2020-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Mazda | BT Pickup | 05/2011-12/2019 | 433MHz | J26E | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mazda | BT-50 | 01/2012-12/2020 | 433MHz | J26E | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mazda | CX-3 | 08/2014-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-3 | 08/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-3 | 01/2020-06/2021 | 433MHz BDEL37140 | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-30 | 01/2019-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-30 | 07/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-5 | 11/2011-12/2022 | 433MHz | J53C/J72A | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-5 | 11/2014-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-7 | 10/2009-12/2018 | 433MHz | J31H | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-9 | 01/2016-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-9 | 01/2013-06/2021 | 433MHz | J50C | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-9 | 10/2006-12/2012 | 433MHz | J50C | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | MX-30 | 01/2021-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | MX-30 | 01/2020-12/2022 | 433MHz BDMC37140 | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | MX-5 | 03/2010-06/2021 | 433MHz | NC/J04C/J12 A | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | MX-5 | 03/2015-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 2 | 12/2007-06/2021 | 433MHz | DY/DE/DJ/J03/J64F | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 3 | 06/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 3 | 06/2014-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|--------------------|--------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mazda | Mazda 3 | 06/2009-05/2014 | 433MHz | BL/BM | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 01/2010-12/2020 | 433MHz | J74G | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2011-12/2020 | 433MHz | GH/GJ/J61A/J71E | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 6 | 01/2008-12/2010 | 433MHz | GH/GJ | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Premacy | 03/2014-12/2018 | 433MHz | J54L | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| McLaren | 500 Series | 01/2015-12/2022 | 433MHz RDE011 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 500 Series | 01/2015-12/2021 | 433MHz RDE018 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 03/2014-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 01/2014-12/2018 | 433MHz 11B0015CP | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 600LT | 01/2018-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 700 Series | 01/2017-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Artura | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| McLaren | Elva | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| McLaren | GT | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | MP4-12C | 01/2011-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | P1 | 01/2013-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Senna | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Senna | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Speedtail | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Sports Series | 01/2015-06/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Super Series | 03/2011-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 06/2018-06/2022 | 433MHz | W177 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 04/2014-05/2018 | 433MHz | W176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | A Class | 01/2012-03/2014 | 433MHz | W176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG | 01/2010-12/2020 | 433MHz | W197 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG | 07/1999-03/2002 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | AMG GT | 08/2019-12/2021 | 433MHz | C190 (A0009053907) | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 11/2018-06/2021 | 433MHz | X290 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 01/2014-06/2022 | 433MHz | C190 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | B Class | 11/2011-01/2019 | 433MHz | W246/W242 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | B Class | 02/2011-12/2022 | 433MHz A0009054104 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | C Class | 01/2021-12/2022 | 433MHz | 206 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 03/2014-05/2018 | 433MHz | W205 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 06/2018-12/2022 | 433MHz | C205 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 04/2007-02/2014 | 433MHz | W204/W203 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 01/2000-12/2006 | 433MHz | W203 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CL Class | 07/2006-06/2019 | 433MHz | C216/C217 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CL Class | 01/2006-06/2015 | 433MHz | C216 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | CL Class | 01/1998-12/2006 | 433MHz | C215 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CLA Class | 05/2019-12/2022 | 433MHz | C118 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | CLA Class | 06/2014-04/2019 | 433MHz | C117 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 12/2012-05/2014 | 433MHz | C117 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLC Class | 01/2008-06/2018 | 433MHz | CL203 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLK Class | 04/2007-06/2018 | 433MHz | W209/W207 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 10/2004-12/2004 | Huf 433MHz | W219 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CLS Class | 09/2004-12/2011 | Continental 433MHz | W219 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | CLS Class | 07/2009-12/2017 | 433MHz | W218 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 01/2017-12/2022 | 433MHz | C257 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Citan | 01/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercedes | Citan | 09/2012-06/2022 | 433MHz | W415 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 06/2014-12/2018 | 433MHz | W212 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 11/2015-12/2022 | 433MHz | W213/BR238 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 01/2002-05/2005 | 433MHz | W211 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | E Class | 06/2005-10/2011 | 433MHz | W211 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | E Class | 01/2014-10/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercedes | E Class | 07/2009-05/2014 | 433MHz | W212/C207 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class AMG | 01/1999-12/2002 | 433MHz | W210 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQA | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQC | 05/2019-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | EQE | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQS | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | EQV | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 06/2018-12/2022 | 433MHz | G463 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 06/2018-06/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 04/2007-05/2018 | 433MHz | G463/461 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 05/2007-06/2009 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Mercedes | GL Class | 01/2013-06/2019 | 433MHz | X166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GL Class | 04/2006-09/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | GL Class | 06/2009-12/2012 | 433MHz | X164 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLA Class | 12/2013-06/2020 | 433MHz | X156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLA Class | 02/2020-12/2022 | 433MHz | H247 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLB Class | 01/2019-12/2022 | 433MHz | X247 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLC Class | 08/2019-07/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 01/2015-07/2019 | 433MHz | X253 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 04/2015-11/2019 | 433MHz | X166/C292 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 10/2018-12/2022 | 433MHz | V167 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLK Class | 01/2008-09/2015 | 433MHz | X204 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLK Class | 10/2015-06/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLS Class | 01/2013-06/2019 | 433MHz | X166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLS Class | 07/2019-12/2022 | 433MHz | X167 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GT | 01/2014-12/2022 | 433MHz | GT | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GT | 09/2018-06/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GT-S AMG | 01/2014-12/2019 | 433MHz | C190 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | M Class | 01/2005-05/2011 | 433MHz | W164 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | M Class | 01/2010-12/2014 | 433MHz | W166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | ML Class | 06/2011-12/2019 | 433MHz | W166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | ML Class | 08/2009-05/2011 | 433MHz | W164 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | ML Class | 12/2004-07/2009 | 433MHz | W164 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | Marco Polo | 01/2014-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Metris | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | R Class | 06/2005-07/2009 | 433MHz | W251 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | R Class | 08/2009-06/2018 | 433MHz | W251 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 07/1999-09/2005 | 433MHz | W220 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | S Class | 10/2005-05/2009 | 433MHz | W221 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | S Class | 07/2020-06/2021 | 433MHz | C217 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 01/2020-12/2022 | 433MHz | W223 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 07/2013-12/2020 | 433MHz | W222/C217 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 06/2009-06/2013 | 433MHz | W221 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class coupe | 01/2003-09/2005 | 433MHz | C215 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Mercedes | S Class coupe | 07/1999-12/2002 | 433MHz | C215 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Mercedes | S Class coupe | 01/2013-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 01/2000-04/2005 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SL Class | 01/2005-06/2012 | 433MHz | W230 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | SL Class | 01/2012-12/2020 | 433MHz | W231 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Roadster | 08/2001-06/2005 | 433MHz | R230 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLC Class | 01/2016-06/2020 | 433MHz | R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLC Class | 07/2020-12/2021 | 433MHz | R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLK | 05/2004-11/2009 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Mercedes | SLK Class | 01/2004-12/2021 | 433MHz | R171, R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLR Class | 04/2004-12/2015 | 433MHz | R199 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLR McLaren | 01/2004-12/2011 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLS Class | 01/2010-06/2019 | 433MHz | 197 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 01/2018-12/2022 | HUF 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | Sprinter | 11/2011-06/2020 | 433MHz | 906 (NVC3) | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 06/2006-10/2011 | 433MHz | W906 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | Sprinter | 01/2006-12/2014 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Mercedes | Sprinter Combi | 11/2011-09/2018 | 433MHz | 906 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter Combi | 10/2018-06/2021 | 433MHz | 906 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | Sprinter Combi | 01/2006-10/2011 | 433MHz | 906 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | T Class | 08/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Mercedes | V Class | 01/2014-12/2021 | 433MHz | W447 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Vario | 01/2012-12/2013 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Mercedes | Vario | 03/2014-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Viano | 07/2003-05/2014 | Continental 433MHz | W639 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | Viano | 06/2014-12/2021 | SCH 433MHz | W639 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Vito | 05/2003-06/2014 | 433MHz | W639 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | Vito | 07/2014-12/2021 | 433MHz | W640 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Vito | 10/2014-12/2020 | 433MHz | VS20 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Mercedes | X Class | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | Pacific | ● | ● |
| Mini | 3-5 Doors Hatch | 01/2014-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-----------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mini | Cabrio | 01/2010-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cabrio | 07/2014-12/2020 | 433MHz | R57 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cabrio | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cabrio | 01/2016-12/2022 | 433MHz | F57 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubman | 09/2009-10/2013 | 433MHz | R55 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubman | 11/2013-12/2021 | 433MHz | F54 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubman | 01/2007-12/2013 | Indirect | R55 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Clubman | 08/2007-08/2009 | 433MHz | R55 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubman | 10/2006-12/2015 | 433MHz 36106856227 | R55 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubvan | 01/2012-12/2013 | Indirect | R55 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Clubvan | 01/2016-12/2019 | 433MHz | F54 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubvan | 07/2012-12/2015 | 433MHz | R55 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Convertible | 01/2009-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Convertible | 01/2014-12/2016 | 433MHz | R57 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Convertible | 01/2016-12/2019 | 433MHz | F57 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Cooper | 01/2014-06/2022 | 433MHz | F55/F56 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Cooper | 01/2006-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Cooper | 09/2007-09/2009 | 433MHz | R58 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cooper S Cabrio | 07/2014-12/2017 | 433MHz | R57 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 01/2009-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 01/2010-12/2013 | Indirect | R60 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Countryman | 07/2014-12/2018 | 433MHz | R60 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 07/2015-12/2022 | 433MHz | F60 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Coupe | 07/2011-06/2018 | 433MHz | R58 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Coupe | 12/2010-09/2019 | 433MHz 36106856227 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Coupe | 01/2011-12/2013 | Indirect | R55 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Electric | 04/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Hatchback | 11/2013-12/2019 | 433MHz | F56 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Mini | 03/2006-12/2019 | 433MHz | F55/F56 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Mini | 01/2009-12/2015 | OYGTSSRE4D 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 01/2014-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | One | 03/2014-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Paceman | 01/2012-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Paceman | 07/2014-06/2018 | 433MHz | R61 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Paceman | 01/2009-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Roadster | 01/2012-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Roadster | 01/2011-04/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Roadster | 05/2014-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | SAV Studie | 07/2014-12/2014 | 433MHz | R58 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mitsubishi | ASX | 01/2014-12/2021 | 433MHz | GA0 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | ASX | 03/2018-03/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Attrage | 10/2013-12/2021 | 433MHz | A10 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | B-SUV | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------------|-----------------|--------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mitsubishi | C-SUV | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Colt | 03/2014-12/2018 | 433MHz | ZM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Colt Plus | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mitsubishi | Delica | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| Mitsubishi | Eclipse Cross | 03/2017-12/2021 | Snap-in 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 01/2017-12/2020 | Clamp-in 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | I | 06/2014-12/2020 | 433MHz | HA | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Mitsubishi | L200 | 01/2014-12/2021 | 433MHz | KA0T/KJOT | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Lancer | 01/2014-12/2022 | 433MHz | CY0 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Lancer Sportback | 01/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 02/2013-12/2021 | 433MHz | A00 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage G4 | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Montero | 01/2014-12/2021 | 433MHz | V80 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 03/2018-12/2021 | Continental 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 01/2018-12/2021 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mitsubishi | Outlander | 01/2014-12/2022 | 433MHz | CW0/GF0 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander PHEV | 03/2018-03/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander PHEV | 04/2014-02/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Pajero | 01/2014-12/2022 | 433MHz | V80 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Pajero Sport | 06/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Shogun | 01/2014-12/2020 | 433MHz | V80 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Shogun Sport | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Shogun Sport | 01/2018-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mitsubishi | Space Mirage | 01/2014-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Mitsubishi | Spacestar | 01/2014-12/2021 | 4250C477 433MHz | GA0 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Spacestar | 01/2014-12/2020 | 433MHz | A00 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Triton | 03/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | i-MiEV | 06/2009-12/2021 | 433MHz | HA0/HAV/HA3W | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| NIO | ES8 | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Nissan | 370Z | 01/2008-07/2014 | 433MHz | C53D/Z34 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | 370Z | 07/2013-06/2021 | PAC 433MHz | RC53D(2)/Z34 | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Nissan | A-Hatch | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Almera | 01/2013-12/2021 | 433MHz | LB1A/G11/B10 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Altima | 10/2018-12/2022 | 433MHz | L33 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Ariya | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Nissan | Armada | 01/2004-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Atleon | 01/2014-12/2019 | 433MHz | F91A/F91B/F91G | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | B-EV | 01/2014-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | C-Hatch | 10/2014-12/2020 | 433MHz | B12L/C13 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Cabstar | 06/2014-12/2019 | 433MHz | F91A/F24 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Cube | 01/2008-09/2014 | 433MHz | Z12/X12B | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-----------|-----------------|--------------------|--------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Cube | 10/2014-06/2020 | 433MHz | X12B | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | E-NV200 | 04/2014-12/2022 | 433MHz | ME0 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Evalia | 01/2012-09/2020 | 433MHz | X11M | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Frontier | 01/2005-12/2014 | Schrader 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Nissan | Frontier | 10/2002-08/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Frontier | 09/2014-06/2019 | 433MHz | H60A | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | GT-R | 01/2016-12/2021 | VDO 433MHz | D52E | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | GT-R | 03/2014-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | GT-R | 09/2007-12/2013 | 433MHz | R35 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | GT-R | 11/2013-12/2022 | PAC 433MHz | D52E | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Interstar | 06/2014-06/2019 | 433MHz | X70 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Juke | 10/2019-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Juke | 01/2019-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Nissan | Juke | 10/2019-12/2022 | 407004CB0B 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Juke | 01/2020-12/2021 | KR5TIS-09DL 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Juke | 03/2014-12/2019 | 407005ZHOA 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Juke | 06/2010-09/2019 | 433MHz | F15/P12C | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Kubistar | 01/2003-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Nissan | Leaf | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 01/2017-09/2018 | 433MHz 407003HNOB | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Leaf | 10/2010-12/2016 | 433MHz | ZE0/B12G | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Micra | 03/2010-12/2019 | 433MHz | B02A/K13 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Micra | 02/2017-12/2022 | 407004CB0B 433MHz | K14 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Micra | 04/2010-01/2017 | 433MHz | K13 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Murano | 01/2015-12/2020 | Russia 433MHz | Z52 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Murano | 10/2014-05/2015 | 433MHz | P42M | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Murano | 06/2014-06/2021 | 433MHz | Z51/Z52/P42M | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Murano | 01/2004-09/2014 | 433MHz | Z51/P42D | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | NP300 | 01/2009-10/2015 | 433MHz Schrader | H61B | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | NP300 | 09/2014-12/2021 | 433MHz | H60A | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | NT500 | 03/2014-06/2019 | 433MHz | F91G | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | NV200 | 04/2014-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | NV200 | 09/2009-12/2021 | 433MHz Continental | K14 | ● | ● | ○ | 0/S | 433MHz | Continental | ● | ● |
| Nissan | NV200 | 08/2015-06/2021 | 433MHz | M20/X11M | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NV200 | 10/2014-07/2015 | 433MHz | M20/X11M | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NV200 | 11/2009-03/2014 | 433MHz Pacific | | ● | ● | ○ | 0/S | 433MHz | Pacific | ● | ● |
| Nissan | NV200 | 01/2016-06/2017 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Nissan | NV250 | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | NV300 | 09/2014-12/2022 | 433MHz | J4/X82 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|----------------|-----------------|-------------------|-----------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | NV400 | 01/2014-12/2022 | 433MHz | X62 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | NV400 Combi | 03/2014-12/2019 | 433MHz | X61F | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Navara | 10/2004-12/2016 | 433MHz | D22/D23/D40/H61B/H60A | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Navara | 01/2017-12/2022 | 433MHz | Y62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Note | 09/2004-12/2021 | 433MHz | J02C/E12/L11E | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 08/2004-08/2012 | 433MHz | R51 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 11/2015-12/2020 | 433MHz | R52/P61B | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 09/2012-10/2015 | 433MHz | P61B | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 01/2004-12/2013 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Nissan | Patrol | 12/2014-12/2022 | 433MHz | Y62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Patrol | 01/2010-11/2014 | 433MHz | Y61/Y62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Pixo | 01/2009-12/2014 | 433MHz | YC5 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Primastar | 01/2014-06/2019 | 433MHz | X83 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Primera | 01/2002-06/2013 | 433MHz | P12/B12L | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Pulsar | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pulsar | 01/2014-12/2019 | 433MHz | C13M/C13/B12L | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | QX50 | 02/2018-12/2022 | PAC 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Qashqai | 01/2021-12/2022 | 407006UAOA 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 06/2019-12/2021 | 433MHz | J10/J11/P32S | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 06/2019-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 06/2018-05/2019 | 433MHz | J10/J11/P32S | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 01/2016-05/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 01/2014-05/2018 | 433MHz | J10/J11/P32S | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 01/2013-12/2013 | 433MHz | J10/J11/P32S | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Rogue | 10/2013-12/2019 | 433MHz | T32 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sentra | 01/2013-12/2022 | 433MHz | L12F | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sunny | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | TERRANO | 06/2014-12/2020 | 433MHz | H79N | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Teana | 01/2014-12/2019 | 433MHz | L42L | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Teana | 02/2013-04/2018 | 433MHz | L33 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Terra | 01/2018-12/2019 | 433MHz | Y62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Tiida | 01/2006-12/2019 | 433MHz | C11/B12/B11C | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Titan | 10/2003-08/2004 | 433MHz | A60 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Townstar Combi | 01/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 09/2016-12/2021 | 433MHz | T32 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 01/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 01/2013-08/2016 | 433MHz | T32/P32R | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Xterra | 01/2012-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Adam | 07/2014-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|---------------------|-----------------|---------------------|-----------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Opel/Vauxhall | Adam | 01/2012-06/2014 | 433MHz | GM 4403 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Adam S & Rocks S | 07/2014-12/2019 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Adam Turbo | 01/2015-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Agila | 06/2014-12/2019 | 433MHz | H0310 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Opel/Vauxhall | Ampera | 01/2015-12/2019 | 433MHz | D2JCI | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Ampera | 07/2005-12/2017 | 433MHz | D1JOI | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Ampera-e | 01/2016-06/2021 | 433MHz | G2KCZ | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 01/2016-12/2020 | 433MHz | C105 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 06/2014-12/2015 | 433MHz | C105 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 11/2010-05/2014 | 433MHz | C105 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 01/2006-10/2010 | 433MHz | C105 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra GTC | 01/2016-12/2018 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra GTC | 01/2015-12/2015 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra H | 01/2004-06/2011 | 433MHz | GM A3300 | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 01/2015-06/2018 | 433MHz | GM P3400 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 06/2014-12/2014 | 433MHz | GM P3400 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 10/2011-05/2015 | 433MHz | GM P3400/ GM A3300 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 01/2009-09/2011 | 433MHz | GM P3400 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J OPC | 06/2014-12/2015 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J OPC | 10/2011-05/2014 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J OPC | 01/2009-09/2011 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra K | 01/2019-12/2022 | 433MHz 13597645 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra K | 10/2015-06/2021 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra LCV | 01/2015-12/2018 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Sports Tourer | 06/2015-12/2020 | 433MHz | D2J0 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Sports Tourer | 01/2015-12/2015 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Van | 08/2019-12/2022 | 433MHz | D2J0 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Van | 01/2015-12/2018 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Van | 01/2014-12/2014 | 433MHz | D2J0/ GM P3400 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Van | 01/2006-12/2013 | 433MHz | GM A3300 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Bolt | 01/2017-06/2020 | 433MHz | G2KCZ | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Cabrio | 06/2014-12/2019 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Cabrio | 01/2013-05/2014 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Cascada | 06/2014-12/2020 | 433MHz | D1A0 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Cascada | 01/2013-05/2014 | 433MHz | D1A0 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Combo | 10/2011-06/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Combo Life | 01/2011-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Combo Tourer | 03/2011-05/2018 | 15 inch 433MHz | 263 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Combo Tourer | 03/2011-05/2018 | 16 inch 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 01/2019-12/2020 | Indirect | F/Mk5 | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Corsa | 11/2014-12/2020 | Non Turbo 433MHz | C0145 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|---------------------|-----------------|--------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Opel/Vauxhall | Corsa | 11/2014-06/2020 | Turbo 433MHz | C0145 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 01/2014-10/2014 | 433MHz | GM S4400 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 01/2006-12/2014 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Corsa | 01/2006-12/2013 | 433MHz | GM S4400 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa Opc | 01/2015-06/2019 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa VXR | 01/2015-12/2018 | 433MHz | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa Van | 01/2014-12/2018 | 433MHz | GM 4530 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Crossland | 01/2017-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Equinox | 01/2017-12/2019 | 433MHz | D2UC | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | GTC | 10/2015-06/2021 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Grandland | 01/2017-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Insignia | 05/2014-09/2015 | 433MHz | GM G3700 | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 06/2017-06/2021 | 433MHz | | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 10/2015-05/2017 | 433MHz | GM G3700 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 01/2008-04/2014 | 433MHz | GM G3700 | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia CT | 01/2015-12/2020 | 433MHz | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia ST | 01/2015-12/2020 | 433MHz | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Karl/Viva | 01/2015-06/2021 | 433MHz | M2J0 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Maloo | 06/2016-12/2017 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Maloo R8 LSA | 01/2014-12/2018 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Meriva B | 04/2010-12/2018 | 433MHz | GM S4470 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Mokka | 08/2015-09/2016 | 433MHz | G1U0 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Mokka | 01/2012-07/2015 | 433MHz | G1U0 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Mokka X | 09/2015-12/2020 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Movano | 06/2010-08/2014 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Opel/Vauxhall | Movano B | 06/2009-06/2021 | 433MHz | X62 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Movano Combi | 06/2010-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Opel/Vauxhall | Signum | 01/2002-12/2009 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | VXR8 | 01/2008-12/2019 | 433MHz | Z2 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vectra | 01/2002-10/2012 | 433MHz | Oe86/ GM Z3200 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vectra Estate | 06/2002-06/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Viva | 01/2015-12/2020 | 433MHz | M2J0 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro B | 01/2015-12/2022 | 433MHz | X82/X83 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro B | 01/2014-12/2014 | 433MHz | X82/X83 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro Combi/Tourer | 01/2019-12/2022 | 433MHz | | ○ | ● | ● | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro Combi/Tourer | 01/2019-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | YARIS | 01/2007-12/2010 | 433MHz | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Opel/Vauxhall | Zafira | 01/2019-12/2020 | Indirect | Life | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Zafira | 01/2005-06/2011 | 433MHz | GM A3370 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira B | 06/2014-06/2021 | 433MHz | B | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira B | 01/2004-05/2014 | 433MHz | B | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira Tourer C | 06/2014-06/2020 | 433MHz | C/ GM P3470 | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira Tourer C | 01/2009-05/2014 | 433MHz | C/ GM P3470 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Pagani | Huayra | 01/2011-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Pagani | Zonda | 01/2011-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Peugeot | 1007 | 01/2004-12/2011 | 433MHz | A08/PF1 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 107 | 01/2012-12/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 108 | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 108 | 01/2014-12/2022 | 433MHz | B3 | ● | ● | ○ | O/S | 433MHz | Pacific | ● | ● |
| Peugeot | 2008 | 01/2013-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 2008 | 02/2013-04/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Peugeot | 2008 | 05/2014-12/2021 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Peugeot | 207 | 11/2005-09/2013 | 433MHz | A7 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 207 | 10/2013-12/2016 | 433MHz | A7 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 207+ | 01/2013-12/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 208 | 01/2012-12/2019 | 433MHz | A9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 208 | 05/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 3008 | 11/2008-08/2013 | 433MHz | T84 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 3008 | 10/2013-12/2021 | 433MHz | T84 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 3008 | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 3008 (LCV) | 01/2008-12/2015 | 433MHz | T84 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 301 | 01/2012-12/2021 | 433MHz | M3/M4 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Peugeot | 307 | 03/2007-12/2008 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 307 | 01/2001-02/2007 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 308 | 04/2007-12/2021 | 433MHz | T7 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 308 | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | 308 | 09/2013-12/2019 | 9802003680 433MHz | T7 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 4008 | 01/2014-12/2021 | 433MHz | J3 | ● | ● | ○ | O/S | 433MHz | Continental | ● | ● |
| Peugeot | 407 | 01/2003-12/2012 | 433MHz | D2 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 408 | 01/2012-12/2019 | 433MHz | T73 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 5008 | 10/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 5008 | 09/2013-12/2019 | 433MHz | T87 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 5008 | 01/2009-08/2013 | 433MHz | T87 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 5008 (LCV) | 01/2009-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 508 | 01/2018-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 508 | 10/2013-12/2019 | 433MHz | W2 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Peugeot | 508 | 09/2010-09/2014 | Continental 433MHz | W2 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 508 (LCV) | 09/2010-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Peugeot | 607 | 10/2004-12/2012 | 433MHz | Z8 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 607 | 09/1999-09/2004 | 433MHz | 6042/Z8 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 807 | 10/2004-12/2016 | 433MHz | V2/80092 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 807 | 02/2002-12/2005 | 433MHz | V2/8052 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Bipper | 01/2013-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Bipper | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Boxer | 12/2013-09/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Peugeot | Boxer | 01/2010-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Boxer Combi | 12/2013-12/2021 | 433MHz | X2/50 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Expert | 01/2011-05/2014 | 433MHz | G9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------|-----------------|----------------------|--------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Peugeot | Expert | 01/2006-12/2010 | 433MHz | G9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Expert | 10/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Expert | 06/2014-12/2019 | 433MHz | G9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | ION | 12/2010-06/2021 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Continental | ● | ● |
| Peugeot | KP1 | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Partner | 03/2016-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | Partner | 06/2014-12/2021 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Partner | 01/2008-05/2014 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | RCZ | 12/2009-09/2013 | 433MHz | T75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | RCZ | 10/2013-12/2017 | 433MHz | T75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Rifter | 06/2018-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Traveller | 10/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Polestar | Polestar 1 | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Porsche | 718 (982) | 01/2016-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 07/2004-01/2012 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (991) | 01/2017-12/2020 | 433MHz | 991 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (991) | 01/2011-12/2016 | 433MHz | 991 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (992) | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 09/2015-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 04/2008-08/2015 | 433MHz | 997 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 01/2004-06/2008 | OYGTSSRE4B 433MHz | 997 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (Turbo) | 01/2007-12/2009 | 433MHz | 997T | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (Turbo) | 01/2017-12/2021 | 433MHz | 991T/992T | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (Turbo) | 01/2010-12/2016 | 433MHz | 991T | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 918 Spyder | 03/2012-06/2018 | 433MHz | 918 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2004-12/2008 | 433MHz | 987 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2012-12/2016 | 433MHz | 981 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 03/2016-06/2022 | 433MHz | 982/982SP | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2009-12/2013 | 433MHz | 987 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Carrera GT | 01/2003-12/2011 | 433MHz | GT | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 09/2017-12/2022 | 433MHz | 9YA | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2011-07/2014 | 433MHz | 92A | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 08/2014-08/2017 | 433MHz | 92A | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 12/2006-12/2010 | 433MHz | 9PA | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2002-12/2006 | 433MHz | 9PA | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 09/2017-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 06/2014-08/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2005-12/2009 | 433MHz | 987/987C | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2009-12/2015 | 433MHz | 987 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 10/2016-06/2022 | 433MHz | 982/982C/CT 4-2 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 05/2014-12/2016 | GTS 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 04/2013-12/2016 | 433MHz | 981 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Porsche | GT3 | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2010-12/2016 | 433MHz | 997 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 03/2006-12/2011 | 433MHz | 996 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 07/2013-12/2021 | 433MHz | P0416/95B | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Mission E | 01/2019-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2021-12/2022 | 433MHz | 971-2 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 09/2017-06/2021 | 433MHz | 970/971 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 09/2013-08/2017 | 433MHz | 970 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2009-08/2013 | 433MHz | 970 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 11/2018-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 01/2019-12/2022 | 433MHz 9J1907275 | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| QOROS | 2 | 01/2016-06/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| QOROS | 3 | 01/2014-12/2019 | 433MHz J523114013 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| QOROS | 3 | 01/2016-06/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| QOROS | 5 | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Renault | Alaskan | 04/2017-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Renault | Alaskan Pickup | 11/2016-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Alpine A110 | 01/2018-12/2022 | 40700-3VUOA 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Alpine A110 | 01/2017-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Arkana | 04/2021-12/2021 | 433Mhz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Renault | Arkana | 01/2019-12/2021 | SD 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Renault | Arkana | 01/2019-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Avantime | 01/2001-12/2003 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Renault | Captur | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Captur | 01/2013-12/2019 | 433MHz | J87 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault | Clio III | 04/2004-05/2014 | 433MHz | X85 | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Renault | Clio IV | 06/2014-12/2019 | 433MHz | X85/X98 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault | Clio IV | 01/2012-05/2014 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault | Clio IV | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Clio V | 01/2019-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Espace | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Espace IV | 01/2002-02/2015 | 433MHz | J81 | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Renault | Espace V | 01/2015-06/2021 | 433MHz | JFC | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Renault | Express | 01/2021-12/2022 | 407009322R 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Renault | Express | 05/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Fluence | 01/2015-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Fluence | 01/2009-06/2021 | 433MHz | L38 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Initiale Paris | 01/2015-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Kadjar | 01/2015-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Renault | Kangoo | 10/2007-06/2021 | 433MHz | X61 | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Renault | Kangoo | 09/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Kangoo | 10/2017-12/2019 | 433MHz | XFG | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Renault | Kangoo Van | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Renault | Kaptur | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Renault | Koleos | 02/2008-12/2015 | LCV 433MHz | H45 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Koleos | 01/2013-07/2016 | Y 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Koleos | 08/2016-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Renault | Koleos | 01/2008-12/2013 | 433MHz | H45 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Laguna II | 12/2000-03/2010 | 433MHz | X74 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Laguna III | 01/2007-12/2016 | 433MHz | X91 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Laguna IV | 04/2015-06/2019 | 433MHz | LFD | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Latitude | 01/2016-12/2019 | 433MHz | L43 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Latitude | 01/2016-06/2018 | 433MHz | LFD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Latitude | 09/2010-12/2015 | 433MHz | L43 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Master | 09/2022-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Master | 11/2009-06/2021 | 433MHz | X62 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Megane | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Megane I | 01/1997-03/2005 | 433MHz | B32/X95/X64 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Megane II | 01/2002-12/2009 | 433MHz | B32/X84 | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane III | 10/2008-01/2017 | 433MHz | X95 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 01/2016-12/2022 | RFB 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Renault | Modus | 04/2004-12/2014 | 433MHz | J77 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Oroch Pickup | 01/2015-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Renault | Scenic I | 01/1997-12/2003 | 433MHz | J64 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Scenic II | 01/2003-07/2010 | 433MHz | J95 | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Renault | Scenic III | 01/2009-12/2018 | 433MHz | J95 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Scenic IV | 01/2016-06/2021 | 433MHz | JFA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Scenic RX4 | 01/2001-12/2003 | JA 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Renault | Spider | 03/2010-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Symbol/Thalia | 01/2013-12/2022 | 433MHz | L52 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Renault | Symbol/Thalia | 01/2019-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Renault | Talisman | 01/2015-06/2021 | RFD 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Renault | Talisman | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Trafic | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Renault | Trafic | 01/2014-12/2021 | 433MHz | X82 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Twingo | 01/2007-06/2021 | 433MHz | X44 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Twingo | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Vel Satis | 09/2001-12/2009 | 433MHz | X73 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Wind | 06/2010-12/2016 | 433MHz | X33 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Renault | Zoe | 07/2019-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Zoe | 09/2012-06/2019 | 433MHz | X10 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Retrofit | CARMAXP425TX | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | CARMAX | ● | ● |
| Retrofit | E-LEAD | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | E-LEAD | ● | ● |
| Retrofit | Honda-CRV | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | S | 433MHz | E-LEAD | ● | ● |
| Retrofit | ORO W401 | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W410-A | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | ORO | ● | ● |
| Retrofit | ORO W410/W403 | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W417-A | 01/2019-12/2019 | 433MHz | | ○ | ● | ○ | A/S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W418-A | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | A/S | 433MHz | ORO | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|----------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Rolls Royce | Black Badge | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Cabrio | 06/2009-12/2011 | 433MHz | RR02 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Cullinan | 01/2018-12/2021 | 433MHz | R31 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Cullinan | 02/2018-12/2022 | YGOTSSRE4A 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Dawn | 01/2016-12/2021 | 433MHz | RR6 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Dawn | 04/2014-02/2022 | OYGTSSRE4D 433MHz | RR6 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Drophead Coupe | 06/2007-12/2018 | 433MHz | RR02 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 01/2020-06/2021 | 433MHz | RR21 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 01/2010-12/2020 | 433MHz | RR04 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 01/2009-12/2010 | 433MHz 36236798726 | RR04 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 01/2017-12/2022 | MRXAG5SP4 433MHz | RR11 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Phantom | 01/2012-12/2017 | 433MHz | RR01 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 02/2003-12/2017 | OYGTSSRE4TC 433MHz | RR01 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 02/2021-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 08/2013-12/2022 | 433MHz | RR5 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Saab | 09-maggio | 01/2006-12/2012 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Saab | 09-maggio | 01/2002-12/2005 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Saab | 09-mar | 09/2002-12/2006 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Saab | 09-mar | 01/2007-12/2015 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 01/2013-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 10/2006-05/2009 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 06/2009-12/2012 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 01/2003-09/2006 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3X | 07/2007-04/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-4X | 01/2011-06/2014 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 11/2006-09/2009 | 433MHz | YE3E | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 07/2002-10/2006 | 433MHz | YE3E | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 10/2009-12/2012 | 433MHz | YS3G | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Saab | 9-7X | 01/2007-12/2009 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Scion | TC | 01/2015-12/2018 | 433MHz | 745L | ● | ● | ○ | O | 433MHz | Pacific | ● | ● |
| Seat | Alhambra | 05/2010-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Altea | 01/2010-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Arona | 03/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Ateca | 09/2016-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Exeo | 06/2013-12/2015 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Seat | Exeo | 01/2009-02/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Ibiza | 01/2010-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Leon | 01/2010-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Mii | 06/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Tarraco | 01/2018-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Toledo | 01/2011-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Citigo | 05/2014-06/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Citigo | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Skoda | Citigo | 01/2011-04/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Fabia | 01/2015-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Fabia | 10/2013-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Fabia | 01/2013-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Kamiiq | 09/2019-12/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Skoda | Karoq | 05/2017-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Karoq | 01/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Kodiaq | 11/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Kodiaq | 01/2016-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Octavia | 10/2012-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Octavia | 01/2013-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Octavia | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Praktik | 01/2013-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Rapid | 01/2013-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Rapid | 05/2015-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Rapid | 05/2012-04/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Roomster | 01/2006-12/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Roomster | 01/2013-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Scala | 01/2019-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Superb | 03/2008-04/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Superb | 01/2013-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Superb | 05/2015-12/2016 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Superb | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Yeti | 06/2009-12/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Yeti | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Smart | Cabrio | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Smart | EQ Forfour | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | EQ Fortwo | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | Forfour | 01/2004-02/2014 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Smart | Forfour | 01/2005-12/2021 | 433MHz | A453 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 01/2007-02/2014 | 433MHz | A451 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 03/2014-06/2021 | 433MHz | A453 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Ssangyong | Actyon | 07/2018-12/2019 | Q200 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Actyon | 01/2013-12/2021 | QJ 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Actyon Sport | 10/2012-12/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | C-CUV | 05/2015-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Chairman | 01/2014-12/2019 | 4199034000 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Korando | 01/2012-12/2019 | C200 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Korando | 01/2018-12/2022 | C300 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Korando | 05/2019-06/2022 | 4199037000 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Kyron | 01/2014-12/2016 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | LUVi | 01/2015-12/2019 | X100 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Musso | 06/2018-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Musso | 01/2016-05/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | New Actyon | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|------------------|-----------------|----------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ssangyong | Nomad | 07/2013-10/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Rexton | 01/2014-12/2017 | Y300 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Rexton | 03/2017-12/2022 | Y400 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Rodius | 01/2014-12/2021 | AJ 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Tivoli | 01/2015-06/2020 | X100 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Tivoli | 06/2019-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Tivoli | 05/2014-12/2014 | X100 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Turismo | 01/2014-12/2022 | AJ 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | XLV | 01/2016-12/2021 | XK 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Subaru | Ascent | 01/2018-12/2022 | 433MHz | HR3 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | BRZ | 01/2014-06/2021 | ZC 433MHz | ZC | ● | ● | ○ | O | 433MHz | Pacific | ● | ● |
| Subaru | C-Concept | 01/2014-06/2018 | 433MHz | VL9 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Crosstrek | 01/2018-12/2021 | 433MHz | HR3 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | FORESTER E-BOXER | 09/2019-06/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Forester | 01/2014-12/2018 | 433MHz | SJ | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Forester | 01/2019-12/2019 | 433MHz | SJ | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Forester | 01/2019-06/2021 | 433MHz | S5/SK | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Impreza | 01/2014-12/2016 | 433MHz | 55A/MF1/ZR1 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Impreza | 09/2016-06/2022 | 433MHz | HR3 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Justy | 01/2014-12/2020 | 433MHz | D71A | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Legacy | 01/2014-12/2017 | 433MHz | EZ5 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Legacy | 05/2017-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Levorg | 01/2015-06/2021 | VM 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Levorg | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Levorg | 03/2021-12/2022 | 433MHz | VN | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Outback | 01/2014-11/2017 | 433MHz | EZ5 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Outback | 12/2017-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Trezia | 01/2014-12/2020 | 433MHz | 217A | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Tribeca | 01/2014-12/2016 | 433MHz | 00X | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | Tribeca | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | WRX | 01/2014-12/2018 | XK 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | WRX | 01/2019-12/2022 | MRXSHR3 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | WRX | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | XV | 01/2012-12/2017 | 433MHz | MF1 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | XV | 03/2017-12/2022 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | XV Crosstrek | 12/2014-02/2018 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Subaru | XV E-BOXER | 01/2020-12/2021 | 433MHz | G5 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Suzuki | Across | 06/2020-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Suzuki | Alivio | 09/2018-12/2019 | 433MHz | YLA | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | Alto | 01/2014-06/2015 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Suzuki | Alto | 06/2014-12/2017 | 433MHz | YC5 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | Alto | 11/2018-06/2020 | 433MHz | YC5/YRA | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | Baleno | 01/2015-06/2021 | 433MHz | YR | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | C-SUV | 08/2020-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Suzuki | C-Wagon | 09/2020-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|---------------|-----------------|-------------------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Suzuki | Carry Van | 04/2015-12/2018 | 433MHz | YV7 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | Celerio | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Suzuki | Celerio | 03/2014-06/2021 | 433MHz | YLA | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | Cultus | 09/2014-09/2020 | 433MHz | YLA | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | Grand Vitara | 06/2014-06/2021 | 433MHz | YT4 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Ignis | 01/2021-12/2022 | 433MHz | MF | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Ignis | 01/2016-06/2021 | 433MHz | YJ | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Jimny | 11/2018-12/2022 | 433MHz | YW5 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Jimny | 06/2014-10/2018 | 433MHz | YR7 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Jimny 3 | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Kizashi | 06/2010-12/2019 | 433MHz | YW1 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | SX4 | 01/2013-12/2021 | 433MHz | YY1, YY3 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | SX4 S-Cross | 01/2022-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | SX4 S-Cross | 01/2013-12/2021 | 433MHz | YAA | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Splash | 09/2013-12/2019 | 433MHz | YV1/YV4/ YV5 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | Swace | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Suzuki | Swift | 07/2021-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Swift | 08/2013-06/2021 | 433MHz | YP6/YP7/YS | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Swift Sport | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | Swift Sport | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | Vitara | 01/2014-06/2021 | 433MHz | YFA/YG4/ YH4 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Vitara | 07/2021-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| TRAUM | SEEK5 | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | TTE | ● | ● |
| Tata | Aria | 01/2016-12/2017 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Bolt | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | GenX Nano | 01/2016-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Harrier | 01/2018-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Hexa | 01/2017-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Indica | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Indigo | 01/2016-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Nexon | 01/2017-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Safari | 01/2016-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Safari Dicor | 01/2016-12/2017 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Safari Storme | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Sumo Gold | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Tiago | 01/2017-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Tigor | 01/2017-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Xenon XT | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tata | Zest | 01/2016-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Tesla | Model 3 | 01/2016-08/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model 3 | 01/2018-12/2021 | 433MHz (10748 1200B) | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 09/2014-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 01/2010-09/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------------|-----------------|--------------------|---|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Tesla | Model X | 10/2014-12/2022 | Continental 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Roadster | 01/2010-12/2012 | Baolong 433MHz | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |
| Tesla | Roadster | 01/2008-12/2010 | Huf 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Toyota | 4 Runner | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | 86 | 04/2012-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | ALLION | 04/2021-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Toyota | Alphard | 02/2012-12/2020 | 433MHz | 480L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Auris | 12/2012-12/2020 | 433MHz | 130A/130L/142L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avalon | 01/2007-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avensis | 10/2008-12/2020 | 433MHz | 312N/445L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avensis | 01/2005-12/2005 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Aygo | 01/2014-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Aygo | 01/2016-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Aygo X | 03/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | C-HR | 01/2016-12/2022 | 433MHz | 560A | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 01/2016-12/2022 | C215 433MHz | 045L | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 01/2014-12/2015 | 433MHz | 045L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 01/2007-12/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Corolla | 01/2019-12/2022 | C215 433MHz | 740A | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | Corolla | 10/2007-12/2018 | 433MHz | 366A/140A/150A/681N/079L/140N/340N/252L/150L/466A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Dyna | 01/2012-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | FJ CRUISER | 05/2006-05/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | FJ Cruiser | 06/2014-12/2020 | 433MHz | 155L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Fortuner | 01/2009-12/2021 | 433MHz | 669L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | GR 86 | 03/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | GR Supra | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| Toyota | GT86 | 09/2012-12/2022 | 433MHz | E88 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Harrier | 09/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Toyota | Hiace | 08/2004-12/2021 | 433MHz | 550N | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Highlander | 01/2013-12/2020 | 433MHz | 397L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Highlander | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Highlander hybrids | 01/2021-12/2022 | C215 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Hilux | 01/2009-12/2021 | 433MHz | 669L/640A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | IQ | 01/2008-12/2019 | 433MHz | 630L/630X | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Kluger | 01/2007-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Kluger | 01/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 10/2015-12/2022 | 433MHz | 215L/611L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 09/2013-09/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 01/2005-08/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser 79 | 10/2015-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|----------------|-------------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | Land Cruiser Prado | 01/2009-09/2017 | 433MHz | 611L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 10/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | MATRIX | 01/2007-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Mirai | 01/2015-12/2020 | PMVC210 433MHz | 470A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Mirai | 01/2019-08/2022 | PMVC215 433MHz | 045L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | PRIUS C | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Previa | 01/2007-12/2020 | 433MHz | 085X/085L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2014-12/2018 | 433MHz | 590L/030A/XW30/XW50/690A/277N | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Proace | 06/2014-12/2022 | 433MHz | G9/K0 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Toyota | Proace | 01/2011-05/2014 | 433MHz | G9 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Toyota | Proace II | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Toyota | Proace II | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Proace Verso | 01/2016-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | RAV4 | 01/2012-09/2019 | 433MHz | 410A/XA40/120L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 01/2018-12/2021 | 433MHz | XA50 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 11/2005-12/2013 | 433MHz | 120L/XA30 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | SOLARA | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sequoia | 01/2008-12/2020 | 433MHz | 200L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sienna | 06/2010-12/2020 | 433MHz | 500N/500L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sienta | 01/2014-12/2019 | 433MHz | 433L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Supra | 03/2019-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Toyota | Tundra | 04/2007-12/2022 | 433MHz | 480A/180L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Urban Cruiser | 06/2007-12/2020 | 433MHz | 260L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Venza | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Venza | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Verso | 02/2009-12/2019 | 433MHz | 770L/151L/595L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Verso-S | 01/2011-12/2017 | 433MHz | 770L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris | 01/2011-12/2021 | C210 433MHz | 020L/850L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris | 07/2020-12/2021 | 433MHz | 020L/850L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris (P9_) | 01/2007-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris Cross | 09/2021-12/2022 | 433MHz | XPB1F | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris GR | 08/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | bZ4X | 03/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Trumpchi | GS8 | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Volkswagen | Amarok | 03/2018-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Amarok | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Amarok | 11/2009-02/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Arteon | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Beetle | 01/2016-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volkswagen | Beetle | 12/2012-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | CC | 01/2018-12/2021 | MQB 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | CC | 06/2011-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | CC | 06/2011-12/2017 | 433MHz | VC17 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | CC | 01/2009-12/2010 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | CC | 01/2009-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volkswagen | Caddy | 01/2014-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Caddy | 12/2003-06/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | California | 11/2019-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Volkswagen | Caravelle | 11/2019-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Caravelle | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Caravelle | 01/2003-12/2018 | 433MHz | VN750 | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Crafter | 01/2006-12/2016 | 433MHz Continental | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Volkswagen | Crafter | 03/2018-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Volkswagen | Crafter | 07/2014-02/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Crafter | 04/2006-06/2014 | 433MHz | VN830 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Crafter | 04/2006-06/2014 | 433MHz | 2E/2F | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volkswagen | Cross Blue | 04/2016-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | EOS | 01/2014-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | EOS | 02/2006-06/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Golf | 10/2008-02/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 03/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 01/2009-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Jetta | 07/2010-06/2020 | 433MHz | VW361 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Jetta | 01/2010-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Magotan | 01/2016-12/2020 | 433MHz 5Q0907275B | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Magotan | 01/2015-12/2016 | 433MHz 1K0907255B | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | Magotan | 01/2008-12/2016 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Magotan | 01/2007-12/2013 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | Multivan | 10/2019-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Volkswagen | Multivan | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Multivan | 03/2004-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | New Beetle | 02/1998-07/2011 | 433MHz | VW314 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | New Beetle | 01/2012-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | New Beetle | 08/2011-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | New Beetle | 01/2006-12/2011 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Passat | 09/2014-06/2021 | 433MHz | B8 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2010-12/2015 | 433MHz | B6/VW471 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2010-12/2014 | 433MHz | | ● | ● | ○ | O | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 03/2005-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Passat | 01/2005-12/2011 | 433MHz | VW451 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volkswagen | Passat CC | 09/2014-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat CC | 03/2008-12/2016 | 3AA907275 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volkswagen | Phaeton | 06/2010-12/2019 | 433MHz | Vh67 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 06/2007-05/2010 | 433MHz | 3D/VW611 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 12/2001-05/2007 | 433MHz | VW611 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 03/2001-12/2007 | 433MHz | 996 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Polo | 09/2017-12/2020 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Polo | 01/2009-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Scirocco | 06/2008-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Scirocco | 01/2008-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Sharan | 03/2010-06/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Sharan | 01/2008-06/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | T-Cross | 01/2019-06/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | T-ROC | 11/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Teramont | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2008-04/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | Tiguan | 01/2008-02/2010 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Tiguan | 01/2007-12/2015 | 433MHz | B6/VW471 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2011-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Tiguan | 01/2016-12/2020 | 433MHz | VW376/5N2 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2012-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan L | 01/2016-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 02/2002-12/2007 | 433MHz | 7L | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2002-12/2006 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 08/2014-12/2022 | 433MHz | 7P5/7P6108 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 08/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Touareg | 01/2010-07/2014 | 433MHz | VW526 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2006-12/2009 | 433MHz | VW526 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touran | 01/2015-12/2022 | 433MHz | VW378 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touran | 07/2010-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Touran L | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touran (LCV) | 07/2010-06/2018 | 433MHz | VW368 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Transporter | 03/2018-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Transporter | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Transporter | 04/2003-02/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Up! | 11/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Up! | 08/2011-12/2018 | 433MHz | VW120 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | XL1 | 07/2013-09/2018 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Volvo | C30 | 01/2011-03/2014 | 433MHz | Y279 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 | 01/2006-12/2010 | 433MHz | Y279 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 Electric | 01/2011-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 Electric | 01/2010-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2011-06/2014 | 433MHz | V70064 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2008-12/2010 | 433MHz | V70064 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2006-12/2007 | 433MHz | V70064 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 01/2011-06/2014 | 433MHz | V40044 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 01/2003-12/2010 | 433MHz | V40044 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 01/2018-06/2021 | 433MHz | V431 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volvo | S60 | 07/2014-12/2020 | 433MHz | Y283 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 02/2013-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S60 | 01/2010-12/2017 | 433MHz | Y283/V634 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 07/2000-02/2010 | 433MHz | P24/V664 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | S70 | 07/2014-10/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S70 | 07/2014-10/2020 | 31341893 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Volvo | S80 | 07/2014-01/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S80 | 01/2010-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 01/2004-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80L | 03/2006-12/2013 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Volvo | S90 | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S90 | 01/2016-06/2021 | 433MHz | V541 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | V40 | 01/2015-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V40 | 01/2012-12/2020 | 433MHz | Y555, Y556 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 01/2011-12/2016 | 433MHz | V5004-124 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 01/2003-12/2010 | 433MHz | V5004-124 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 | 11/2017-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | V60 | 09/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V60 | 01/2014-12/2019 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 | 01/2008-06/2014 | 433MHz | Y352 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V70 | 07/2014-12/2019 | 433MHz | Y285 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V70 | 01/2008-06/2014 | 433MHz | Y285/V714 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V70 | 01/2000-12/2007 | 433MHz | Y285/V764 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | V90 | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V90 | 01/2015-12/2022 | 433MHz | V542 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC40 | 01/2017-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 01/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 01/2008-06/2021 | 433MHz | Y413 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 07/2014-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2010-06/2014 | 433MHz | Y381 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2008-12/2009 | 433MHz | Y381 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2003-12/2007 | 433MHz | Y381 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC90 | 01/2015-06/2021 | 433MHz | V526 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 01/2002-05/2018 | 433MHz | Y289 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 (LCV) | 06/2015-06/2017 | 433MHz | Y289 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 (LCV) | 06/2015-06/2017 | 433MHz | V526 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| ZOTYE | Domy SR7 | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| ZOTYE | Domy SR9 | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| ZOTYE | Domy X5 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Zotye | ● | ● |
| ZOTYE | Domy X7 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Zotye | ● | ● |
| ZOTYE | E Series | 01/2016-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| ZOTYE | Meet5 | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | TTE | ● | ● |
| ZOTYE | T Series | 01/2016-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|------------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| ZOTYE | T300 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| ZOTYE | T500 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Zotye | ● | ● |
| ZOTYE | T600 | 01/2013-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ZOTYE | T600 Coupe | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| ZOTYE | T600 NEW | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| ZOTYE | T700 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| ZOTYE | T800 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| ZOTYE | Z Series | 01/2016-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| ZOTYE | Z360 | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| ZOTYE | Z560 | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| ZOTYE | Z700 | 01/2013-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |